

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21001282/QPA3Q2

Date: 12/05/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900077635
<b>Claimant Vehicle No :</b>	SHF119R	<b>Insured Vehicle No :</b>	SMJ2110X
Date of Loss:	25/01/2021	Nature of Claim:	TP
		Claim No:	7175056281SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHF119R</b>		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2F33455
Reg. Date:	20/12/2019 (Man. Year: 2019)	Chassis No:	JTDKB3FU903089225
Colour:	Maroon	Odometer:	117360 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,092.44	2,268.85	9,823.59	81.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,570.00	1,050.00	2,520.00	70.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>15,662.44</b>	<b>3,318.85</b>	<b>12,343.59</b>	<b>78.81</b>
<b>+ Loss of Use (5.5 x S\$50.00/day) (S\$)</b>		275.00		
<b>+ Car Rental (5.5 x S\$112.35/day) (S\$)</b>		617.93		
<b>+ Doc/Search Fee (S\$)</b>		7.00		
<b>Nett Liability (S\$)</b>		<b>4,218.78</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,150.00</b>		

### INSPECTION

Date of Assignment:	26/01/2021	
Date Inspected:	26/01/2021	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	4.0 days	

Adjuster: OI SUN PIN

Manager: CHEW HSIAO TONG

5/12/2021

## Adjuster Report

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GUARD ,RR BUMPER LOWER (DISC 25%)	Crumpled	374.50 F	*280.88 F
2	1		*CLIPS PIECE ,FRT & RR BUMPER (DISC 25%) (10 PCS)	Necessary	45.00 F	*33.75 F
3	1		*RETAINER ,RR BUMPER ,LH (DISC 25%)	Broken	132.60 F	*99.45 F
4	1		*NAME PLATE (PRIUS) LUGGAGE COMPARTMENT (DISC 25%)	Necessary	54.60 F	*40.95 F
5	1		*NAME PLATE (HYBRID) LUGGAGE COMPARTMENT (DISC 25%)	Necessary	54.60 F	*40.95 F
6	1		*EMBLEM SUB-ASSY REAR (DISC 25%)	Necessary	47.90 F	*35.93 F
7	1		*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB (DISC 25%)	Crumpled	913.60 F	*685.20 F
8	1		*COVER ,RR BUMPER ASSY (DISC 25%)	Crumpled	485.60 F	*364.20 F
9	1		*PAD ,RR BUMPER ,RH & LH 3 (DISC 25%)	Necessary	11.00 F	*8.25 F
10	1		*PAD ,RR BUMPER ,RH & LH 2 (DISC 25%)	Necessary	4.00 F	*3.00 F
11	1		*PAD ,RR BUMPER ,RH & LH 1 (DISC 25%)	Necessary	4.00 F	*3.00 F
12	1		*PAD ,RR BUMPER ,CTR (DISC 25%) (3 PCS)	Necessary	33.00 F	*24.75 F
13	1		*LAMP ASSY ,REAR LH (DISC 10%)	Cracked	293.60 F	*264.24 F
14	1		*LENS & BODY ,REAR COMBINATION LAMP NO.2 (DISC 10%)	Crumpled	261.00 F	*234.90 F
15	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
16	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
17	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
18	1		*WIRE ,LUGGAGE ROOM	Serviceable	170.70 F	*- F
19	1		*SENSOR REVERSE	Serviceable	180.00 F	*- F
20	1		*LAMP ASSY ,REAR LH	Serviceable	293.60 F	*- F
21	1		*SOCKET & WIRE SUB-ASSY REAR COMBINATION LAMP	Serviceable	52.30 F	*- F
22	1		*COVER ,REAR COMBINATION LAMP ,LH	Serviceable	69.90 F	*- F
23	1		*LENS & BODY ,REAR COMBINATION LAMP LH	Serviceable	339.60 F	*- F
24	1		*COVER ,REAR FLOOR UNDER CENTER	Serviceable	229.90 F	*- F
25	1		*COVER ,REAR FLOOR UNDER LH	Serviceable	241.90 F	*- F
26	1		*COVER ,REAR FLOOR UNDER RH	Serviceable	175.10 F	*- F
27	1		*REAR BUMPER REFLECTOR ASSY ,REFLEX ,LH	Serviceable	39.00 F	*- F
28	1		*REAR BUMPER REFLECTOR ASSY ,REFLEX RH	Serviceable	39.00 F	*- F
29	1		*COVER GUARD RR BUMPER LOWER	Serviceable	22.00 F	*- F
30	1		*SEAL ,RR BUMPER ,LH	Serviceable	118.30 F	*- F
31	1		*SEAL ,RR BUMPER ,RH	Serviceable	118.30 F	*- F
32	2		*STOPPER ,RR BUMPER ,RH & LH	Serviceable	4.50 F	*- F
33	1		*RETAINER ,RR BUMPER RH	Serviceable	132.60 F	*- F
34	1		*TAILGATE BOARD ASSY	Serviceable	259.20 F	*- F
35	1		*TAILGATE TRIM ,LOWER	Serviceable	225.20 F	*- F
36	1		*TAILGATE TRIM LH	Serviceable	95.60 F	*- F
37	1		*TAILGATE TRIM RH	Serviceable	95.60 F	*- F
38	1		*TAILGATE TRIM ,UPPER	Serviceable	52.10 F	*- F
39	1		*REAR BUMPER REINFORCEMENT	Serviceable	332.70 F	*- F
40	1		*PANEL SUB-ASSY ,FENDER REAR LH	Serviceable	871.50 F	*- F
41	1		*LINER ,REAR FENDER LH	Serviceable	139.80 F	*- F
42	1		*TAIL GATE PANEL SUB-ASSY ,BACK DOOR	Serviceable	1,147.80 F	*- F
43	1		*SEALANT SIKAFLEX	Serviceable	37.00 F	*- F
44	1		*END PANEL SUB-ASSY ,BODY LOWER BACK	Serviceable	651.00 F	*- F
45	1		*CAP SUB-ASSY ,WHEEL	Serviceable	211.50 F	*- F
46	2		*HUB & BEARING ASSY ,RH & LH	Serviceable	668.90 F	*- F
47	1		*TYRE	Serviceable	126.74 F	*- F
48	1		*WHEEL DISC	Serviceable	1,879.40 F	*- F
49	1		*COVER SUB-ASSY ,REAR QUARTER PILLAR LH	Serviceable	207.30 F	*- F

F=Franchise part.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	12,092.44 2,268.85
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING & BODY WORK	New	676.00	400.00
2	SPRAY PAINT	New	1,924.00	400.00
3	TO REPAIR REAR FENDE LOWER PANEL LH	New	250.00	150.00
4	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	20.00
5	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
6	TO TRANSFER REAR TAILGATE MECHANISM	New	120.00	60.00
7	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	0.00
8	TO REPLACE SUNDRY PARTS	New	100.00	0.00
9	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
10	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			3,570.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >