



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving TPVD Chevrolet Aveo (SJQ7941E)

Date of Loss 24 January 2021

Time of Loss 17.24

Loss Description SHA3591R (INSD) HIT REAR OF SJQ7941E (TP)

Comment

Workshop Details

Total Rebate Amount 9258

Nett Loss Amount \$7,242.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work completion * 20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details



Vehicle Registration#	SJQ7941E	Purchase Date	<div>dd/mm/yyyy</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>26/05/2009</div> <div></div>
Mileage	<div>195004</div>	Age of Vehicle	11

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<div>2008</div>
Make	TPVD Chevrolet	<div>CHEVROLET</div>

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	Tan Bee Huat	<div></div>
Date of Birth	11 September 1965	<div>dd/mm/yyyy</div> <div></div>

Model CATEGORY	Agency POLICY INFORMATION	CHEVY AVEO 1.4AT 4D
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="KL1SA69719B620163"/>
Engine No		<input type="text" value="F14D37340451"/>
Engine Capacity		<input type="text" value="1399"/>
Sum Insured		<input type="text" value="0"/>
Market Value		<input type="text" value="16500"/>

CATEGORY Age	FNOL INFORMATION 55	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="dd/mm/yyyy"/> 
License Expiration Date		<input type="text" value="dd/mm/yyyy"/> 

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Address	Not Entered By User, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>
Gender	Unknown	<input type="text" value="▼"/>
Marital status	Unknown	<input type="text" value="▼"/>
Identification #	S1688558D	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

28/01/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver
Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

10

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts





Add

Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR BONNET LID COVER	Bent	0	580.1	No		10			522.09	Reviewing
<input type="checkbox"/>		0	1		REAR BONNET LID LOCK	Dented	0	48.5	No		10			43.65	Reviewing
<input type="checkbox"/>		0	1		REAR BONNET LOGO	Necessary	0	68.1	No		10			61.29	Reviewing
<input type="checkbox"/>		0	1		REAR BONNET EMBLEM "AVEO"	Necessary	0	25.2	No		10			22.68	Reviewing
<input type="checkbox"/>		0	1		REAR BONNET EMBLEM "LS"	Necessary	0	15.5	No		10			13.95	Reviewing
<input type="checkbox"/>		0	1		REAR BONNET EMBLEM "CHEVROLET"	Necessary	0	48.3	No		10			43.47	Reviewing
<input type="checkbox"/>		0	1		REAR END PANEL	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BUMPER	Buckled	0	520.6	No		10			468.54	Reviewing

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR BUMPER REINFORCEMENT	Cracked	0	308.1	No		10			277.29	Reviewing
<input type="checkbox"/>		0	1		SET REAR BUMPER CLIPS	Necessary	0	30	No		10			27	Reviewing
<input type="checkbox"/>		0	1		SIDE BUMPER RETAINER (2PCS)	Damaged	0	35	No		10			31.5	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER LOWER LIP	Cracked	0	360.5	No		10			324.45	Reviewing





Labour

Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY	0	450	0	0	Reviewing	
<input type="checkbox"/>		0		TO PUTTY, APPLY PRIMER & RESPRAYING	0	600	0	0	Reviewing	
<input type="checkbox"/>		0		RUST PROOFING	0	30	0	0	Reviewing	
<input type="checkbox"/>		0		CHECK WIRING FUNCTION	0	15	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 4 DAYS	Reviewing		0		
<input type="checkbox"/>		0	1 SET REAR REVERSE SENSOR	Reviewing		200	DENTED	
<input type="checkbox"/>		0	REAR BOOT WEATHER STRIP (\$90.20)	Reviewing		45.1	CUT	

EDIT	SR NO	(50%) NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount	\$0.00			Adjusted Claim Amount	\$3,176.01		
CATEGORY	ESTIMATE	ADJUSTED					
Spare Parts	\$0.00	\$1,835.91					
Labour	\$0.00	\$1,095.00					
Miscellaneous	\$0.00	\$245.10					

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add	Approve	Deny	Submit All				
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	FINAL LUMP SUM	Reviewing	2500		

Submit for Review