

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:**

CC4/AIG17021548/KGA3Q2-1

**Date:**

17/05/2021

**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1700034233

**Claimant Vehicle No :** SLH5262T**Insured Vehicle No :**

SBP96R

Date of Loss: 09/11/2017

Nature of Claim:

TP

Claim No:

0257700407SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLH5262T**

Make &amp; Model: HONDA VEZEL, 1.5 X (A)

Engine No:

L15B4037662

Reg. Date: 08/11/2016 (Man. Year: 2016)

Chassis No:

RU11117656

Colour: Metallic Silver

Odometer:

84945 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Dunlop 4 mm

Rear Left Side:

Dunlop 4 mm

Front Right Side: Dunlop 4 mm

Rear Right Side:

Dunlop 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,092.50	919.68	1,172.82	56.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	690.00	440.00	38.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,222.50</b>	<b>1,609.68</b>	<b>1,612.82</b>	<b>50.05</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,250.00</b>		

<b>Nett Amount (S\$)</b>	<b>3,222.50</b>	<b>1,250.00</b>	<b>1,972.50</b>	<b>61.21</b>
<b>+ Loss of Use (3.0 x S\$50.00/day) (S\$)</b>		150.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,402.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,400.00</b>		

INSPECTION

Date of Assignment: 10/11/2017

Date Inspected: 10/11/2017

Estimated Period of Repair: 3.0 days

Inspected At: Supreme Auto Service Pte Ltd (HQ)  
176 Sin Ming Drive #02-01, Sin Ming Autocare  
Singapore 575721

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## Recommended Parts

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE ,KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS	New	300.00	200.00
2	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	80.00	30.00
3	TO APPLY WATER PROOF SEALANT ON AFFECTED AREAS	New	80.00	0.00
4	TO APPLY PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	450.00	400.00
5	TO TRANSFER DOOR ACCESSORIES	New	120.00	60.00
6	TO DIAGNOTIC AND RESETTNG	New	100.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,130.00</b>	<b>690.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >