

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CS/MSG21001287/T1TF3Q2  
**Date:** 11/05/2021

**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001465142
<b>Claimant Vehicle No :</b>	SBS6572C	<b>Insured Vehicle No :</b>	SKL2520J
Date of Loss:	22/01/2021	Nature of Claim:	TP
		Claim No:	252472

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SBS6572C</b>		
Make & Model:	MERCEDES-BENZ CITARO O530, 6.4 L AT TURBO ABS (A)	Engine No:	902926C1087007
Reg. Date:	01/07/2015 (Man. Year: 2015)	Chassis No:	WEB62808323128614
Colour:	Green	Odometer:	403310 km
Engine Capacity:	6374 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8/8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8/8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	364.00	364.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	642.00	450.00	192.00	29.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,006.00</b>	<b>814.00</b>	<b>192.00</b>	<b>19.09</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>70.42</b>	<b>56.98</b>	<b>13.44</b>	<b>19.09</b>

**Nett Amount (S\$)****1,076.42****870.98****205.44****19.09**INSPECTION

Date of Assignment: 27/01/2021

Date Inspected: 27/01/2021

Estimated Period of Repair: 1.0 days

Inspected At:

SBS Transit Ltd (YCK)  
3 Yio Chu Kang Crescent  
Singapore 786010**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 11 May 2021)	
<b>Parts:</b>	N/A	MERCEDES-BENZ CITARO O530 6.4 L AT TURBO ABS (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SBS6572C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER W/RR FOGLAMP OS	Cracked	364.00 F	*364.00 F
F=Franchise part.						
<b>Total Parts (\$\$)</b>					<b>364.00</b>	<b>364.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CONTRACTOR LABOUR COST	New	450.00	450.00
2	WORKSHOP ADMIN COST	New	192.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>642.00</b>	<b>450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >