

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001294/KGS3Q2
Date: 18/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100508622-03
Claimant Vehicle No :	SLG7494H	Insured Vehicle No :	SLN2544T
Date of Loss:	25/01/2021	Nature of Claim:	TP
		Claim No:	8500959235SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG7494H		
Make & Model:	VOLVO S60, 1.5 T2 (A)	Engine No:	B4154T51747839
Reg. Date:	12/10/2016 (Man. Year: 2016)	Chassis No:	YV1FS28C0H2425791
Colour:	Metallic Pearl White	Odometer:	64332 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Hankook 4 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 4 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,071.80	2,214.54	2,857.26	56.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	650.00	800.00	55.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,521.80	2,864.54	3,657.26	56.08
Approved Total (Overridden) (S\$)		2,300.00		

(S\$)	6,521.80	2,300.00	4,221.80	64.73
+ GST 7.00/7.00% (S\$)	456.53	161.00	295.53	64.73
Nett Amount (S\$)	6,978.33	2,461.00	4,517.33	64.73
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,643.00		

INSPECTION

Date of Assignment: 27/01/2021

Date Inspected: 01/02/2021

Inspected At: Ricardo Auto Centre Pte Ltd (HQ)
160 Sin Ming Drive, #02-02, Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Cracked	1,922.80 F	*1,762.40 FL
2	1		*REAR BUMPER SPOILER -UPPER	Dented / Warped	618.20 F	*618.20 FL
3	1		*REAR BUMPER SPOILER -LOWER	Serviceable	512.60 F	*- FL
4	1		*REAR BUMPER CENTER RETAINER	Serviceable	107.80 F	*- FL
5	4		*REAR BUMPER SIDE RETAINER LH & RH	Serviceable	286.00 F	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Repair	1,544.40 F	*- FL
7	10		*REAR BUMPER CLIPS	Necessary	80.00 F	*80.00 FL
					Sub Total (\$)	5,071.80
					- List Item Discount on L Items 0.00/10.00% (\$)	0.00
					Total Parts (\$)	5,071.80
						2,460.60
						2,214.54

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CUT ,WELD & STRAIGHTEN REAR PORTION OF CAR CAUSED BY ACCIDENT ,ADJUST & REPLACE DAMAGE PARTS	New	500.00	250.00
2	TO SPRAY PAINT ON REPAIRED AREA	New	500.00	400.00
3	TO PROGRAM REAR SENSOR SETTING	New	450.00	0.00
Gross Labour Cost (\$\$)			1,450.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >