

ASS. REC. BY: Taylor

REF: U4/11121001304/T1693

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: G86746/86 Yr Regn: 2017, Aug  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toyota Hiace c.c. 2982  
 Colour: Silver A/C: Insured / Std / NI / NA  
 Sp. Reading: 84396 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JTFHT02P800220320  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: NI / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 195/R15  
 R: 175

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 958K  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: Melvin  
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Doublestar  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 6 mm L/Bal. 6 mm  
 L/Bal. 6 mm R/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 27/1/21 @ 1315  
 Survey held at Wah Hong  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Frt N/S, Frt, O/S  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Report limit 935K</u>

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_  
 Report Format: \_\_\_\_\_  
 Lump Sum / L.B.L. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_  
 Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S + RS. \$ \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_  
 TOTAL \_\_\_\_\_



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)  
 Email: motor@wahhong.sg  
 (199806235M)

Vehicle No. **GBG4618G TOYOTA HIACE TURBO 5 DR MT**

Page No. 1-1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	<b><u>PARTS (LIST ITEMS)</u></b>			
1	Windscreen		1218.00	crn ✓
1	Windscreen moulding		279.00	neu ✓
1	Wiper top garnish		781.00	de ✓
2	Wiper top side garnish LH/RH @ 2*\$614		1228.00	LH-de ✓, RH ✓
1	Wiper top garnish rubber seal		55.00	rub ✓
1	Bonnet		790.00	bt ✓
1	Bonnet lock		191.00	bt ✓
1	Bonnet logo badge		62.00	neu ✓
2	Bonnet hinge LH/RH @ 2*\$122		244.00	bt ✓
2	Front top corner panel LH/RH @ 2*\$231		462.00	bt ✓
1	Front both top corner inner panel		579.00	bu ✓
2	Headlamp LH/RH @ 2*\$790		1580.00	crn ✓
1	Headlamp lower bracket Lh		62.00	de ✓
1	Center grille base		790.00	mis ✓
1	Center grille top outer		279.00	mis ✓
1	Center grille lower outer		271.00	mis ✓
1	Center lower grille		390.00	mis ✓
1	Front bumper		579.00	mis ✓
2	Front bumper side Bracket LH/RH @ 2*\$231		462.00	crn ✓
2	Front bumper towing cover LH/RH @ 2*\$62		124.00	mis ✓
2	Front fog lamp cover LH/RH @ 2*\$191		191.00	mis ✓
1	Wiper tank		181.00	de ✓
1	Coolant tank		379.00	re crn ✓
1	Support panel		790.00	bt ✓
1	Support panel top garnish Lh		379.00	de ✓
1	Support panel top garnish rubber seal Lh		379.00	rub ✓
1	Front top reinforcement		479.00	bt ✓
1	Front top reinforcement inner panel		790.00	?
1	Front top reinforcement side beam Lh		379.00	bt ✓
1	Front lower reinforcement		379.00	bt ✓
1	Front lower reinforcement side beam LH		371.00	bu ✓
2	Front door LH/RH @ 2*\$1718		3436.00	bt ✓
1	Front door upper and lower hinge LH/RH @ 2*\$190		380.00	LH bt ✓, RH ?
2	Step up garnish LH/RH @ 2*\$379		758.00	crn ✓
2	Front side mirror assy LH/RH @ 2*\$1219		2438.00	crn ✓

Vehicle No. **GBG4618G TOYOTA HIACE TURBO 5 DR MT**

Page No. 1-2

1	Front door Lh inner trim board	790.00	?
1	Front door Lh inner top corner garnish	379.00	X
1	Front door Lh window glass	781.00	bu✓
1	Front door Lh weatherstrip	279.00	?
1	Front both door window outer lower garnish	179.00	X
1	Front door Lh lock	579.00	?
1	Inner door panel top garnish LH	321.00	?
2	Wheel arch outer rubber seal LH/RH @ 2*\$122	244.00	24-?, RH ✓
1	Front Lh door front pillar	790.00	bt ✓
1	Front LH door pillar outer center	370.00	?
1	Front LH door pillar outer lower	371.00	?
1	Front door LH step up inner panel	271.00	bt ✓
1	Front corner inner panel back LH	62.00	?
1	Front corner inner panel front LH	32.00	?
1	Fuse box base	231.00	an ✓
1	Front side connector cover Lh	171.00	an ✓
1	Wire harness whole assy	2301.00	?
2	Front/Rear Rim cover RH @2*371	742.00	Fit RH mis ✓, Rear RH ✓
1	Tail lamp rh	379.00	an ✓
2	Rear bumper retainer LH/RH @ 2*\$182	364.00	X
		31771.00	
		-25%	-7942.75
			23828.25
<b>SPECIAL NETT ITEMS</b>			
1	Front bumper clips	35.00	30nd ✓
1	Front grille clips	30.00	count ✓
1	ERP sticket	10.00	nd ✓
2	Front door company sticker LH/RH @2*\$15	30.00	ant ✓
1	Side panel and door RH company stickers	300.00	200 ant ✓
1	Wiper top cover garnish clips	25.00	15 an ✓
1	Front carplate	35.00	an ✓
1	Coolant	60.00	?
1	Front windscreen solar film	300.00	? 200
1	Front windscreen Sealant	60.00	an ✓
1	Rear bumper clips	35.00	X
1	Headlamp light/low beam bulb LH	30.00	an ✓
1	Headlamp signal light bulb LH	20.00	an ✓
1	Headlamp parking light bulb LH	20.00	an ✓
<b>Total Parts</b>		<b>24818.25</b>	



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)  
 Email: motor@wahhong.sg  
 (199806235M)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Vehicle No. GBG4618G TOYOTA HIACE TURBO 5 DR MT

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	<b>LABOUR</b>		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	2400.00	1800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	2000.00	1800
3	To remove and re-fix/replace wiring harness system at accident damaged area and check all electrical & component for proper function	300.00	150? photo
4	To perform anti-rust treatment on affected areas	150.00	60
5	To remove and replace front windscreen	150.00	120
6	To remove, replace and focus headlamp beams	60.00	40
7	To remove and refit front seat in order to repair	100.00	60? photo
8	To remove and refit roots lining & upholster garnish	100.00	60? photo
9	To remove and refit/replace front door LH window glass, fitting, trimming, garnish and etc.	100.00	50
10	To remove and refit/replace front door RH window glass, fitting, trimming, garnish and etc.	100.00	50
11	To remove and replace air-con condenser, pipes, vacuum and recharging gas	120.00	100
12	To remove and refit dashborad and related parts	300.00	200? photo
13	Wheel computer alignment	80.00	✓
	Labour Total :	5960.00	
	TOTAL (PARTS & LABOUR):	30778.25	

Taufik  
 97495749  
 WP' 27/1/21 & 13/15  
 L/S Resurvey after repair.  
 To check repair limit  
 To check liability and  
 inform w/s.  
 12 days  
 taufik@lkkamp.com