



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)
 Email: motor@wahhong.sg
 (199806235M)

Vehicle No. **GBG4618G TOYOTA HIACE TURBO 5 DR MT**

Page No. 1-1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	Windscreen		1218.00	crn ✓ 987.90.
1	Windscreen moulding		279.00	new ✓ 110.70.
1	Wiper top garnish		781.00	de ✓ 495.03
2	Wiper top side garnish LH/RH @ 2*\$614 150		1228.00	LH-de ✓, RH-de ✓ 150.
1	Wiper top garnish rubber seal		55.00	out ✓
1	Bonnet		790.00	bt ✓
1	Bonnet lock		191.00	bt ✓
1	Bonnet logo badge		62.00	new ✓
2	Bonnet hinge LH/RH @ 2*\$122 90		244.00	bt ✓ 180.
2	Front top corner panel LH/RH @ 2*\$231		462.00	bt ✓
1	Front both top corner inner panel		579.00	R ✓
2	Headlamp LH/RH @ 2*\$790		1580.00	crn ✓
1	Headlamp lower bracket Lh		62.00	de ✓
1	Center grille base		790.00	mis ✓ 610.30.
1	Center grille top outer		279.00	mis ✓ 193.50
1	Center grille lower outer		271.00	mis ✓ 159.30.
1	Center lower grille		390.00	mis ✓ 178.10
1	Front bumper		579.00	mis ✓
2	Front bumper side Bracket LH/RH @ 2*\$231 151		462.00	crn ✓ 302
2	Front bumper towing cover LH/RH @ 2*\$62		124.00	mis ✓
2	Front fog lamp cover LH/RH @ 2*\$191		191.00	mis ✓
1	Wiper tank		181.00	de ✓
1	Coolant tank		379.00	crn ✓ 210
1	Support panel		790.00	bt ✓ 585
1	Support panel top garnish Lh		379.00	de ✓ 249.80
1	Support panel top garnish rubber seal Lh		379.00	out ✓ 81.75
1	Front top reinforcement		479.00	bt ✓ 289
1	Front top reinforcement inner panel		790.00	? bt ✓ 556.
1	Front top reinforcement side beam Lh		379.00	bt ✓ 150.
1	Front lower reinforcement		379.00	bt ✓ 279.
1	Front lower reinforcement side beam LH		371.00	R ✓
2	Front door LH/RH @ 2*\$1718 1415		3436.00	bt ✓ 2830.
1	Front door upper and lower hinge LH/RH @ 2*\$190 110		380.00	LH bt ✓, RH bt ✓ 220.
2	Step up garnish LH/RH @ 2*\$379 290		758.00	crn ✓ 580.
2	Front side mirror assy LH/RH @ 2*\$1219 325		2438.00	crn ✓ 790

Vehicle No.

GBG4618G TOYOTA HIACE TURBO 5 DR MT

Page No. 1-2

1	Front door Lh inner trim board	790.00	? cna / 495
1	Front door Lh inner top corner garnish	379.00	x nn
1	Front door Lh window glass	781.00	buw
1	Front door Lh weatherstrip	279.00	? dis
1	Front both door window outer lower garnish	179.00	x wt
1	Front door Lh lock	579.00	? bt / 495
1	Inner door panel top garnish LH	321.00	? dl / mis
2	Wheel arch outer rubber seal LH/RH @ 2*\$122	244.00	24-? / RH fu
1	Front Lh door front pillar	790.00	bt / 390
1	Front LH door pillar outer center	370.00	? bt / 270
1	Front LH door pillar outer lower	371.00	? bt / 200
1	Front door LH step up inner panel	271.00	bt / 190
1	Front corner inner panel back LH	62.00	? bt
1	Front corner inner panel front LH	32.00	? bt
1	Fuse box base	231.00	an
1	Front side connector cover Lh	171.00	an
1	Wire harness whole assy	2301.00	? fu / 1285.10
2	Front/Rear Rim cover RH @ 2*371 85	170 742.00	Fit RH mis / Rear RH cna
1	Tail lamp rh	379.00	cna / 170
2	Rear bumper retainer LH/RH @ 2*\$182	364.00	x nn
		31771.00	
		-25%	-7942.75
		23828.25	
SPECIAL NETT ITEMS			
1	Front bumper clips	35.00	30nd /
1	Front grille clips	30.00	cont /
1	ERP sticket	10.00	nd /
2	Front door company sticker LH/RH @ 2*\$15	30.00	nt /
1	Side panel and door RH company stickers	300.00	200 nt
1	Wiper top cover garnish clips	25.00	15 wt
1	Front carplate	35.00	mis
1	Coolant	60.00	? nd
1	Front windscreen solar film	300.00	? 200
1	Front windscreen Sealant	60.00	nd
1	Rear bumper clips	35.00	x nn
1	Headlamp light/low beam bulb LH	30.00	an
1	Headlamp signal light bulb LH	20.00	an
1	Headlamp parking light bulb LH	20.00	an
Total Parts		24818.25	

20688.48
15516.36

740.



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)
 Email: motor@wahhong.sg
 (199806235M)

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Vehicle No. GBG4618G TOYOTA HIACE TURBO 5 DR MT

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	2400.00	1800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	2000.00	1800
3	To remove and re-fix/replace wiring harness system at accident damaged area and check all electrical & component for proper function	300.00	150? photo ✓
4	To perform anti-rust treatment on affected areas	150.00	60
5	To remove and replace front windscreen	150.00	120
6	To remove, replace and focus headlamp beams	60.00	40
7	To remove and refit front seat in order to repair	100.00	60? photo ✓
8	To remove and refit roots lining & upholster garnish	100.00	60? photo ✓
9	To remove and refit/replace front door LH window glass, fitting, trimming, garnish and etc.	100.00	50
10	To remove and refit/replace front door RH window glass, fitting, trimming, garnish and etc.	100.00	50
11	To remove and replace air-con condenser, pipes, vacuum and recharging gas	120.00	100
12	To remove and refit dashborad and related parts	300.00	200? photo; inform w/s.
13	Wheel computer alignment	80.00	✓
	Labour Total :	5960.00	
	TOTAL (PARTS & LABOUR):	30778.25	

Taufik
 97495749
 wp' 27/11/21 & 13/15
 L/S Repairing after repair.
 To check repair limit
 To check liability and
 12 days
 taufik@lkkamp.com

4570.



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. GBG4618G TOYOTA HIACE TURBO 5 DR MT

Page No. 3

QTY	DESCRIPTION (SUPPLEMENTARY)	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Front door RH step up inner panel		271.00	bt /
1	Front door RH inner trim board		790	de / 495
1	Wheel arch panel top garnish LH		371	de / 180
1	A pillar inner garnish		402	cm / 220
1	Dashboard inner support		1019	bt / 650
1	Front reinforcement LH side support panel		231.00	bt / 151
1	Front top reinforcement LH side beam top support		241.00	bt /
1	Front LH door rear pillar panel		X790.00	repair
1	Airconditional assy		3739.00	cm / 1219.40
1	Aircon blower		979.00	cm / 865.80
1	Front inner panel		1211.00	bue / 484.90
1	Front headlight wiring cover		190.00	cm /
1	Cabin wiring cover		231.00	cm /
1	Cabin floor panel		1218.00	bue / 618
			11683.00	
			-25%	-2920.75
			8762.25	
<u>SPECIAL NETT ITEMS</u>				
<u>LABOUR</u>				
		Total Parts	8762.25	

5817.10
4362.82



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. GBG4618G TOYOTA HIACE TURBO 5 DR MT

Page No. 4

QTY	DESCRIPTION (SUPPLEMENTARY PART 2)	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT	
<u>PARTS (LIST ITEMS)</u>					
1	Front door LH step up outer top panel	Missing	272.00	195 ht	
1	Front door LH step up outer lower panel		272.00		
1	Front door RH step up outer top panel		272.00	195 ht	
1	Front door RH step up outer lower panel		272.00		
1	Front door RH top pillar inner panel		479.00	XR	
1	Wiper top garnish inner panel LH		279.00	de	
1	LH chassis member sub-frame front		369.00	212.	
1	LH chassis member sub-frame rear top		279.00	44.60	
1	LH chassis member sub-frame rear bottom		279.00	44.60	
1	Bonnet stand		62.00	ms	
1	Engine mounting LH		dis 231.00	164.11	
1	Engine mounting RH		dis 231.00	144.10.	
			3297.00	1540.41	
			-25% -824.25		1155.30
			2472.75		
<u>SPECIAL NETT ITEMS</u>					
1	Front door window glass LH solar film (Vcool)		150.00	nu	
<u>LABOUR</u>					
			2622.75	150.	
Total Parts			2622.75		

15516.36
 740
 4570.
 4362.82.
 1155.30
 150

 26494.48
 45821.200.

12 days #