

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21001307/ABS3Q2
Date: 18/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210001838
Claimant Vehicle No :	SJV8337S	Insured Vehicle No :	GBE2728X
Date of Loss:	22/01/2021	Nature of Claim:	TP
		Claim No:	6169853366SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV8337S		
Make & Model:	HONDA FREED, 1.5 G (A)	Engine No:	L15A2334092
Reg. Date:	09/02/2010 (Man. Year: 2008)	Chassis No:	GB31033688
Colour:	Red	Odometer:	139979 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,983.35	6,292.90	6,690.45	51.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,850.00	2,480.00	1,370.00	35.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,833.35	8,772.90	8,060.45	47.88
Approved Total (Overridden) (S\$)		7,000.00		

(S\$)	16,833.35	7,000.00	9,833.35	58.42
+ GST 7.00/7.00% (S\$)	1,178.33	490.00	688.33	58.42
Nett Amount (S\$)	18,011.68	7,490.00	10,521.68	58.42
+ Car Rental (9.0 x S\$120.00/day) (S\$)		1,080.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,572.00		
Global Sum Settlement (S\$)		8,300.00		

INSPECTION

Date of Assignment: 26/01/2021

Date Inspected: 26/01/2021

Inspected At: Success United Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
Singapore 417921

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER ASSY	Deformed	625.10 FL	*625.10 FL
2	2		*FRT BUMPER SIDE HOLDER L/R	Necessary	38.42 FL	*38.42 FL
3	1		*FRT BUMPER TOW HOOK COVER	Deformed	27.02 FL	*27.02 FL
4	2		*HEADLAMP ASSY L/R	Not Necessary	1,396.40 FL	*- FL
5	1		*FRT GRILLE ASSY	Cracked	645.15 FL	*385.00 FL
6	1		*FRT BUMPER REINFORCEMENT	Bent	348.50 FL	*348.50 FL
7	1		*RADIATOR SUPPORT PANEL ASSY	Not Necessary	550.00 FL	*- FL
8	1		*RADIATOR ASSY	Not Necessary	1,530.60 FL	*- FL
9	1		*AIRCON CONDENSER	Not Necessary	795.60 FL	*- FL
10	1		*REAR BOOT LID HONDA LOGO	Necessary	27.40 FL	*27.40 FL
11	1		*REAR BOOT LID FREED EMBLEM	Necessary	55.71 FL	*55.71 FL
12	1		*REAR BOOT LID OUTER HANDLE	Not Necessary	193.72 FL	*- FL
13	1		*REAR BOOT LID WEATHERSTRIP	Cut	139.80 FL	*139.80 FL
14	2		*REAR BOOT LID DAMPER L/R	Not Necessary	276.00 FL	*- FL
15	1		*REAR BOOT LID MECHANISM LOCK	Damaged	312.90 FL	*265.00 FL
16	1		*THIRD BRAKE LIGHT	Not Necessary	210.90 FL	*- FL
17	1		*REAR WIPER MOTOR	Not Necessary	312.00 FL	*- FL
18	1		*REAR WIPER ARM	Cut	85.00 FL	*85.00 FL
19	1		*REAR WIPER BLADE	Cut	75.00 FL	*75.00 FL
20	1		*REAR BOOT LID INNER TRIM BOARD	Cracked	419.50 FL	*298.00 FL
21	1		*REAR END PANEL	Dented	523.10 FL	*523.10 FL
22	1		*REAR END PANEL INNER TOP GARNISH	Deformed	98.10 FL	*98.10 FL
23	2		*REAR LAMP L/R	Cracked	1,036.00 FL	*1,036.00 FL
24	1		*REAR BUMPER	Distorted	590.47 FL	*590.47 FL
25	1		*REAR BUMPER TOW HOOK COVER	Deformed	28.00 FL	*28.00 FL
26	1		*REAR FLOOR PANEL	Repair	1,295.30 FL	*- FL
27	2		*REAR FENDER INNER TRIM GARNISH L/RH	Not Necessary	762.00 FL	*- FL
28	1		*REAR NO.PLATE LAMP	Not Necessary	61.50 FL	*- FL
29	1		*REAR BOOT HANDLE SWITCH	Not Necessary	215.60 FL	*- FL
30	1		*REAR WINDSCREEN	Shattered	1,280.00 FL	*1,280.00 FL
31	1		*REAR WINDSCREEN MOULDING	Necessary	150.00 FL	*150.00 FL
32	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
33	2		*SET FRT & REAR NO PLATE W/FRAME	Bent	90.00 FS	*90.00 FS
34	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
35	1		*REAR BOOT LID	Distorted	1,521.90 FL	*1,288.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	2		*HEADLAMP BRACKET L/R	Cracked	90.00 FL	*90.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					16,126.69	7,783.62
- List Item Discount on L Items 20.00/20.00% (S\$)					3,143.34	1,490.72
Total Parts (S\$)					12,983.35	6,292.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REINSTALL AIRCON PARTS ,VACUM REFILL GAS	New	250.00	0.00
2	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	1,800.00	1,200.00
3	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	1,600.00	1,200.00
4	TO REMOVE ,REPLACE & TRANSFER REAR BOOT LID COMPONENTS	New	200.00	80.00
Gross Labour Cost (S\$)			3,850.00	2,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >