

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21001321/EVF3E2

Date: 09/03/2021

REFERENCE

Insured/Claimant:	TAN HAN QI	Policy No:	1900117812	Claim No:	9354059405SG
Date of Loss:	27/01/2021	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM6890K	Engine No:	3A92UHT5347
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Chassis No:	MMBSTA13AKH002063
Reg. Date:	10/07/2019 (Man. Year: 2019)	Odometer:	23950 km
Colour:	Grey		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$57,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,558.41	4,228.70	4,329.71	50.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,480.00	3,310.00	2,170.00	39.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,038.41	7,538.70	6,499.71	46.30
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	13,438.41	6,938.70	6,499.71	48.37
+ GST 7.00/7.00% (S\$)	940.69	485.71	454.98	48.37
Nett Amount (S\$)	14,379.10	7,424.41	6,954.69	48.37

INSPECTION

Date of Assignment: 28/01/2021

Date Inspected: 28/01/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*WHEEL, DISC LHF	Cut	687.00 FL	*687.00 FL
3	1		*WHEEL, DISC RHF	Not Necessary	687.00 FL	*- FL
4	1		*FENDER, FR RH	Dented	497.00 FL	*497.00 FL
5	1		*FACE, FR BUMPER	Broken	703.00 FL	*703.00 FL
6	1		*BRACKET, FR BUMPER, LH	Not Necessary	13.00 FL	*- FL
7	1		*BRACKET, FR BUMPER, RH	Broken	13.00 FL	*13.00 FL
8	1		*GARNISH, FR BUMPER, RH	Not Necessary	127.00 FL	*- FL
9	5		*CLIP, FR BUMPER	Necessary	20.00 FL	*20.00 FL
10	1		*SHAFT AS, FR AXLE DRIVE, RH	Not Necessary	1,201.00 FL	*- FL
11	1		*KNUCKLE, RH	Not Necessary	365.00 FL	*- FL
12	1		*BEARING, FR WHEEL HUB RH	Not Necessary	121.00 FL	*- FL
13	1		*SNAP RING, FR WHEEL HUB RH	Not Necessary	8.00 FL	*- FL
14	1		*HUB ASSY, FR WHEEL RH	Not Necessary	240.00 FL	*- FL
15	1		*CROSSMEMBER, FR AXLE, NO.1	Not Necessary	864.00 FL	*- FL
16	1		*ARM ASSY-FR SUSP, LWR RH	Bent	278.00 FL	*278.00 FL
17	1		*BAR, FR SUSP STABILIZER	Not Necessary	282.00 FL	*- FL
18	1		*STRUT, FR SUSP RH	Bent	452.00 FL	*452.00 FL
19	1		*BEARING, FR SUSP STRUT	Not Necessary	9.00 FL	*- FL
20	1		*HOSE, FR BRAKE, RH	Not Necessary	39.00 FL	*- FL
21	1		*SENSOR, FR ABS RH	Not Necessary	171.00 FL	*- FL
22	1		*GEAR & LINK ASSY, STEERING	Not Necessary	1,444.00 FL	*- FL
23	1		*END ASSY, TIE ROD	Not Necessary	52.00 FL	*- FL
24	1		*UNPAINTED BODYKITS	Broken	1,643.00 FS	*1,643.00 FS
25	1		*EMBLEM ECO	Necessary	17.00 FS	*17.00 FS
26	1		*HEADLAMP ASSY, RH	Cut	660.00 FL	*660.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,613.00	4,990.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	2,054.59	761.30
Total Parts (\$\$)	8,558.41	4,228.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, FRT BUMPER BODY KIT & RHF FENDER. REPAIR LHF FENDER	New	1,800.00	900.00
2	RESPRAY FRT BUMPER, FRT BUMPER BODY KIT, RHF FENDER & LHF FENDER	New	1,400.00	1,400.00
3	RENEW LHF SPORT RIM & TYRE	New	30.00	30.00
4	RENEW RHF SPORT RIM & TYRE	New	30.00	-
5	SUPPLY LHF TYRE-BRIDGESTONE S001 - 185/55R15	New	260.00	260.00
6	SUPPLY RHF TYRE - BRIDGESTONE S001 - 185/55R15	New	260.00	0.00
7	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
9	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
10	RENEW FRT U/CARRIAGE RH	New	450.00	450.00
11	RENEW STEERING RACK & PINION ASSY	New	450.00	0.00
12	RENEW FRT X-MEMBER ASSY	New	450.00	0.00
13	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	0.00
Gross Labour Cost (\$\$)			5,480.00	3,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >