

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21001323/UPA3Q2**Date:** 05/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800122640
<b>Claimant Vehicle No :</b>	PC6707A	<b>Insured Vehicle No :</b>	SKV9678P
Date of Loss:	14/01/2021	Nature of Claim:	TP
		Claim No:	7145180679SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>PC6707A</b>	Engine No:	D7E12016832
Make & Model:	VOLVO B7R, 7.1 (A)	Chassis No:	YV3R6R629HA185790
Reg. Date:	30/10/2017 (Man. Year: 2017)	Odometer:	191321 km
Colour:	Silver		
Engine Capacity:	7146 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D)
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7/7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7/7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,358.00	0.00	7,358.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,580.00	2,400.00	2,180.00	47.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>11,938.00</b>	<b>2,400.00</b>	<b>9,538.00</b>	<b>79.90</b>
<b>+ Loss of Use (3.0 x S\$150.00/day) (S\$)</b>		450.00		
	<b>Nett Liability (S\$)</b>	<b>2,850.00</b>		

INSPECTION

Date of Assignment:	28/01/2021		
Date Inspected:	03/02/2021	Inspected At:	UNIMOTOR COMPANY NO 1 KAKI BUKIT AVE 6 #01-94 Singapore 417883
Estimated Period of Repair:	3.0 days		

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER O/S	Repair	1,850.00 F	*- F
2	1		*REAR BUMPER REFLECTOR O/S	Serviceable	58.00 F	*- F
3	1		*REAR COMPARTMENT PANEL REAR O/S	Repair	3,800.00 F	*- F
4	1		*REAR VERTICAL PANEL O/S	Repair	1,650.00 F	*- F
F=Franchise part.						
				Total Parts (S\$)	7,358.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO SPRAY RUST PROOFING	New	80.00	0.00
2	LABOUR FOR PANEL BEATING	New	2,500.00	1,200.00
3	TO PUTTY & SPRAY PAINTING	New	2,000.00	1,200.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,580.00</b>	<b>2,400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >