

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/GRB21001325/KVD3Q2
Date: 08/06/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLB6849B	Insured Vehicle No :	SLK7154T
Date of Loss:	26/01/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000432

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB6849B		
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Engine No:	M16A2024940
Reg. Date:	19/04/2016 (Man. Year: 2016)	Chassis No:	TSMLEYE21S00199719
Colour:	Metallic Red	Odometer:	109246 km
Engine Capacity:	1586 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,674.97	6,459.05	7,215.92	52.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,970.00	2,760.00	4,210.00	60.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,644.97	9,219.05	11,425.92	55.34
Approved Total (Overridden) (S\$)		8,500.00		

(S\$)	20,644.97	8,500.00	12,144.97	58.83
+ GST 7.00/7.00% (S\$)	1,445.15	595.00	850.15	58.83
Nett Amount (S\$)	22,090.12	9,095.00	12,995.12	58.83

INSPECTION

Date of Assignment: 28/01/2021

Date Inspected: 28/01/2021

Estimated Period of Repair: 9.0 days

Inspected At:

160 SIN MING DRIVE #05-09

Repairer: Hc Auto Pte Ltd (HQ)

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2021)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB6849B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN GLASS MOLDING	Necessary	57.90 FL	*57.90 FL
2	1		*TAIL GATE	Bent	1,004.15 FL	*1,004.15 FL
3	1		*TAIL GATE WEATHERSTRIP	Dented	132.40 FL	*132.40 FL
4	2		*TAIL GATE HINGE	Repair	50.20 FL	*- FL
5	2		*TAIL GATE DAMPER	Serviceable	207.10 FL	*- FL
6	1		*TAIL GATE INNER TRIM BOARD	Mtg Cracked	325.80 FL	*325.80 FL
7	1		*TAIL GATE INNER LOCK	Distorted	151.85 FL	*151.85 FL
8	1		*TAIL GATE INNER LOCK CATCH	Repair	22.50 FL	*- FL
9	1		*TAIL GATE OUTER HANDLE	Serviceable	35.20 FL	*- FL
10	1		*TAIL GATE REFLECTOR	N/S Mtg Cracked	508.00 FL	*254.55 FL
11	1		*TAIL GATE SUZUKI LOGO	Necessary	20.20 FL	*20.20 FL
12	1		*TAIL GATE VITARA EMBLEM	Necessary	30.20 FL	*30.20 FL
13	1		*TAIL GATE SUZUKI EMBLEM	Necessary	18.30 FL	*18.30 FL
14	1		*TAIL GATE ALL GRIP EMBLEM	Necessary	39.40 FL	*39.40 FL
15	1		*REAR BUMPER FASCIA	Bent / Torn	971.50 FL	*971.50 FL
16	10		*REAR BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
17	1		*REAR BUMPER REINFORCEMENT	Bent	225.60 FL	*225.60 FL
18	1		*REAR BUMPER REFLECTOR	N/S Broken	75.50 FL	*37.75 FL
19	1		*REAR BUMPER BRACKET	N/S Bent	173.10 FL	*86.55 FL
20	1		*REAR BUMPER SIDE RETAINER	N/S Cracked	32.90 FL	*16.45 FL
21	1		*REAR BUMPER LOWER GARNISH	Missing	282.05 FL	*282.05 FL
22	1		*N/S REAR FENDER	Repair	359.80 FL	*- FL
23	1		*N/S REAR FENDER OUTER GARNISH	Serviceable	144.65 FL	*- FL
24	1		*N/S REAR FENDER INNER GARNISH	Buckled	463.80 FL	*463.80 FL
25	1		*N/S REAR FENDER WHEEL ARCH GARNISH	Distorted	109.80 FL	*109.80 FL
26	1		*TAIL LAMP	N/S Cracked	723.90 FL	*361.95 FL
27	1		*TAIL LAMP PANEL	N/S Bent	273.20 FL	*136.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR END PANEL	Bent	414.85 FL	*414.85 FL
29	1		*REAR PANEL INNER GARNISH	Dented	150.25 FL	*150.25 FL
30	1		*REAR PANEL LOWER GARNISH	Dented	162.45 FL	*162.45 FL
31	1		*REAR AIR DUCT	Distorted	58.90 FL	*29.45 FL
32	1		*N/S REAR SHOCK ABSORBER	Serviceable	294.40 FL	*- FL
33	1		*N/S REAR AXLE BEAM	Serviceable	1,520.00 FL	*- FL
34	1		*N/S REAR KNUCKLE ARM	Serviceable	718.00 FL	*- FL
35	1		*N/S REAR KNUCKLE ARM BEARING	Serviceable	645.55 FL	*- FL
36	1		*N/S REAR DRIVE SHAFT	Serviceable	651.95 FL	*- FL
37	1		*REAR EXHAUST BOX	Bent	605.45 FL	*605.45 FL
38	1		*REAR EXHAUST BOX COVER (ALUMINIUM)	Dented	55.45 FL	*55.45 FL
39	2		*REAR EXHAUST BOX MOUNTING	Distorted	50.20 FL	*50.20 FL
40	1		*REAR EXHAUST BOX CENTRE	Repair	777.25 FL	*- FL
41	2		*REAR NO.PLATE LAMP	Serviceable	42.50 FL	*- FL
42	1		*REAR FLOOR PANEL	Bent	250.90 FL	*250.90 FL
43	2		*TOOLS BOX LH & RH	Serviceable	54.80 FL	*- FL
44	1		*REAR SPARE TYRE BOARD	Serviceable	620.40 FL	*- FL
45	1		*REAR SPEAKER BOARD	Cracked	650.50 FL	*650.50 FL
46	1		*REAR TOOL BOARD	Serviceable	87.70 FL	*- FL
47	1		*REAR GEAR BOX MEMBER (ALUMINIUM)	Serviceable	445.00 FL	*- FL
48	1		*REAR PANEL SEAL	Necessary	45.00 FS	*30.00 FS
49	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
50	1		*REAR WINDSCREEN INNER GUM	Necessary	60.00 FS	*40.00 FS
51	1		*REAR CAMERA	Serviceable	450.00 FS	*- FS
52	1		*REAR NO PLATE	Serviceable	70.00 FS	*- FS
53	4		*REAR REVERSE SENSOR	Dented (2 PCS ONLY)	343.20 FS	*171.60 FS
54	1		*REAR BUMPER LOWER CENTER CAP	Missing	70.50 FL	*70.50 FL
55	1		*REAR BUMPER FOG LAMP CENTER COVER	Missing	67.55 FL	*67.55 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,906.75	7,550.95
- List Item Discount on L Items 15.00/15.00% (S\$)	2,231.78	1,091.90
Total Parts (S\$)	13,674.97	6,459.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES	New	2,200.00	1,200.00
2	TO PUTTY AND SPRAY PAINTING	New	1,800.00	1,000.00
3	TO CHECK WIRING	New	120.00	20.00
4	COATING	New	1,200.00	0.00
5	TO RE-SEAL ANTI RUST	New	320.00	60.00
6	TO TRANSFER TAIL GATE	New	120.00	60.00
7	REMOVE AND REFIX REAR REVERSE SENSOR	New	120.00	60.00
8	REMOVE AND REFIX REAR CUSHION SEAT ,GARNISH ,CARPET ,ETC	New	280.00	120.00
9	REMOVE & REFIX N/S REAR UNDERCARRIAGE & GEAR BOX	New	450.00	0.00
10	TO CHECK WHEEL ALIGNMENT	New	120.00	60.00
11	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
12	REMOVE AND REFIX EXHAUST BOX	New	120.00	60.00
Gross Labour Cost (S\$)			6,970.00	2,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >