



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX  
SINGAPORE 069110

INV No. AC2101654

INV Date 15/03/2021

Reference CS/EQI21001331/R1vd3e2

Code EQI

#### PROFESSIONAL SERVICE FEE

Vehicle No. SMQ 6601H  
Insured Veh. GBD 4600Y  
Claim No. DM21HO00155/JT  
Policy No.  
Accident Date 25/01/2021  
Inspection Date 28/01/2021

Description	Total
Survey Inspection	300.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>300.00</b>
<b>GST (7%)</b>	<b>21.00</b>
<b>Grand Total</b>	<b>321.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**KHM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD  
5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX SINGAPORE 069110

Ref: CS/EQI21001331/R1vd3e2

Date: 15/03/2021

Code: EQI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBD 4600Y	<b>Veh. Inspected</b>	SMQ 6601H
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	DM21HO00155/JT	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	JAIME TAY	<b>Assign Date</b>	28/01/2021

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	NISSAN SERENA 1.2L HIGHWAY STAR	<b>c.c</b>	1198
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2019
<b>Chassis No.</b>	JN1EBAC27Z0000261	<b>Colour</b>	GOLD
<b>Odometer</b>	30589 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/60 R16	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	195/60 R16	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	195/60 R16	BRIDGESTONE	6 mm
<b>L/H Rear Tyre</b>	195/60 R16	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	25/01/2021	<b>Inspection Date</b>	28/01/2021
<b>Survey held at</b>	913 BUKIT TIMAH ROAD		
<b>Repairer</b>	TAN CHONG MOTOR SALES PTE LTD		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **11 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 6601H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	HANDLE-PULL TAILGATE (N)	DEFORMED	19.60	19.60
2	LICENSE PLATE LAMP @\$80.20 (N)	SERVICEABLE	160.40	-
1	HARNESS-CORNER SENSOR REVERSE (N)	SERVICEABLE	194.40	-
1	LAMP COMB RR, LH (N)	SERVICEABLE	560.30	-
2	GROMET TAILGATE @\$4.90 (N)	NECESSARY	9.80	9.80
2	GROMET TAILGATE @\$4.90 (N)	NECESSARY	9.80	9.80
1	CAMERA ASSY ALL VIEW (REAR) (N)	SERVICEABLE	750.00	-
1	INSULATOR HEAT S/TYRE HOUSING (N)	TO REPAIR SEE LABOUR	132.10	-
1	PROTECTOR-LH REAR FENDER (N)	SERVICEABLE	117.70	-
1	PROTECTOR-RH FENER REAR (N)	SERVICEABLE	117.70	-
6	CLIP FENDER @\$1.30 (N)	NECESSARY	7.80	7.80
1	DRAFTER-AIR LH REAR (N)	SERVICEABLE	67.40	-
2	VALVE LH REAR FENDER @\$4.90 (N)	SERVICEABLE	9.80	-
1	RR PANEL-END LOWER (N)	BENT	215.00	215.00
1	LH REAR WHEELHOUSE FINISHER (N)	CRACKED	638.00	638.00
1	GARNISH END PANEL (N)	CRACKED	52.30	52.30
1	BOX-LUGGAGE S/TYRE HOUSING (N)	SERVICEABLE	279.60	-
1	BOARD ASSY S/TYRE HOUSING (N)	DEFORMED	528.00	528.00
1	GARNISH ASSY LH REAR (TOP) WHEELHOUSE (N)	SERVICEABLE	144.20	-
1	FACE-RR BUMPER (N)	DEFORMED	1,414.00	1,414.00
1	BRACKET-BUMPER LH REAR (N)	SERVICEABLE	32.50	-
1	BRACKET-BUMPER RH REAR (N)	SERVICEABLE	32.50	-
1	REAR BUMPER LH SIDE BRACKET (N)	SERVICEABLE	32.50	-
1	REAR BUMPER LH SIDE BRACKET (N)	SERVICEABLE	26.00	-
1	REAR BUMPER RH SIDE BRACKET (N)	SERVICEABLE	32.50	-
1	REAR BUMPER RH SIDE BRACKET (N)	SERVICEABLE	26.00	-
5	GROMET BUMPER @\$1.60 (N)	NECESSARY	8.00	8.00
27	CLIP BUMPER / FINISHER @\$1.30 (N)	NECESSARY	35.10	35.10
12	GROMET BUMPER @\$2.70 (N)	NECESSARY	32.40	32.40

Report Ref No. CS/EQI21001331/R1vd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SHIELD ASSY LH REAR SIDE (N)	TO REPAIR SEE LABOUR	384.90	-
1	SHIELD ASSY REAR SIDE RH (N)	TO REPAIR SEE LABOUR	384.90	-
1	MOUL-RR BUMPER LH (BLACK) (N)	SERVICEABLE	359.70	-
1	MOUL-RR BUMPER RH (BLACK) (N)	SERVICEABLE	359.70	-
1	DOOR BACK (TOP) (N)	BUCKLED	4,015.00	4,015.00
1	A FIN BACK DOOR CENTER (N)	DEFORMED	797.20	797.20
1	DOOR BACK (N)	DEFORMED	1,742.00	1,742.00
1	W/STRIP-BK DOOR (TOP) (N)	NECESSARY	141.80	141.80
1	WEATHER STRIP BODY (N)	NECESSARY	106.40	106.40
1	HINGE ASSY-BACK RH (N)	SERVICEABLE	73.20	-
1	HINGE ASSY-BACK LH (N)	SERVICEABLE	73.20	-
1	A FIN BACK DOOR (SERENA) (N)	CRACKED	797.20	797.20
1	A LOCK LIFT LOWER (N)	BENT	199.80	199.80
1	STRIKER-TAIL GATE (TOP) (N)	BENT	34.80	34.80
1	A LOCK LIFT (TOP) (N)	SERVICEABLE	199.80	-
1	BRACKET, LOCK (TOP) TAILGATE (N)	SERVICEABLE	39.00	-
1	GARNISH ASSY, RR TOP WIPER (N)	CRACKED	192.90	192.90
1	FINISHER TAILGATE REAR TRIMBOARD (N)	CRACKED	297.90	297.90
1	FIN-TAIL GATE (LOWER) CENTER (N)	CRACKED	187.50	187.50
1	AIR SPOILR-RR, LH REAR (N)	SERVICEABLE	189.20	-
1	BRKT RR SPOILER LH (N)	SERVICEABLE	103.00	-
1	AIR SPOILR-RR, RH (N)	SERVICEABLE	189.20	-
1	BRKT RH REAR SPOILER (N)	SERVICEABLE	103.00	-
1	EMBLEM REAR (N)	NECESSARY	79.90	79.90
1	EMBLEM-REAR (N)	NECESSARY	50.90	50.90
1	EMBLEM-REAR (N)	NECESSARY	94.40	94.40
1	S/TYRE HOUSING (N)	TO REPAIR SEE LABOUR	492.10	-
1	LAMP COMB RR, RH (N)	CRACKED	560.30	560.30
1	FINISHER RH REAR WHEELHOUSE (N) (ADDITIONAL)	CRACKED	638.00	638.00
1	CARPET FLOOR (N) (ADDITIONAL)	DEFORMED	545.20	545.20
1	COVER HIGH MTG 3RD BRAKE LIGHT GARNISH (N) (ADDITIONAL)	CUT	61.20	61.20

Report Ref No. CS/EQI21001331/R1vd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-3,835.74	-2,702.44
			15,342.96	10,809.76
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	PAPAGO GS360DVR (SN)	MISSING	357.00	357.00
1	REAR LICENCE PLATE (SMART PLATE WITH CASING) LONG (SN)	BENT	50.00	50.00
1	MUFFLER ASSY (SN)	SERVICEABLE	828.00	-
1	GASKET-EXHAUST (SN)	NOT NECESSARY	4.40	-
1	MOUNTING EXHAUST (SN)	NOT NECESSARY	21.80	-
1	MOUNTING EXHAUST (SN)	NOT NECESSARY	11.20	-
2	SENSOR ASSY REAR BUMPER (OUTER) @\$232.00 (SN)	SERVICEABLE	464.00	-
2	COVER REAR BUMPER SENSOR (OUTER) @\$96.30 (SN)	SERVICEABLE	192.60	-
2	SENSOR BUMPER CENTER @\$232.00 (SN)	NECESSARY	464.00	464.00
2	COVER REAR BUMPER CENTER SENSOR @\$72.50 (SN)	NECESSARY	145.00	145.00
1	LAMP ASSY-STOP 3RD (SN)	SERVICEABLE	237.50	-
1	ARM ASSY-RR WIPER (SN)	SERVICEABLE	59.40	-
1	REFILL-RR WIPER (SN)	NOT NECESSARY	12.50	-
1	COVER-ARM, BACK WIPER (SN)	SERVICEABLE	11.20	-
1	MOTOR-WIPER (SN)	SERVICEABLE	479.70	-
1	END PANEL TOP (SN)	BENT	242.50	242.50
1	SUNDRIES (SN)	NECESSARY	200.00	40.00
1	COOLING UNIT LH REAR (SN) (ADDITIONAL)	CRACKED	900.00	900.00
			4,680.80	2,198.50
	<b><u>LABOUR</u></b>			
	CONDUCT CONSULT, RESET & PROGRAMING.		240.00	240.00
	PULL / STRAIGHTEN CHASSIS.	NOT NECESSARY	350.00	-
	REMOVE / INSTALL BLOWER & HEATER UNIT TO FACILITATES REPAIRS.		240.00	240.00
	REMOVE / INSTALL EXHAUST MUFFLER ASSY.	NOT NECESSARY	240.00	-
	REMOVE / INSTALL SEAT & CUSHION CARPET.		240.00	240.00
	REMOVE / INSTALL & TEST REAR REVERSE CAMERA.		120.00	120.00
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 05.		600.00	120.00

Report Ref No. CS/EQI21001331/R1vd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE / REPAIR WIRE HARDNESS (REVERSE SENSOR).	NOT NECESSARY	240.00	-
	SUPPLY & INSTALL REVERSE SENSOR.		110.00	110.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 05.		500.00	100.00
	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN.		150.00	150.00
	RENEW REAR WINDSCREEN GLASS ASSY.		240.00	240.00
	REPAIR LH / RH REAR FENDER AND RENEW TAILGATE (TOP / BOTTOM), END PANEL, S/TYRE HOUSING, REAR BUMPER. INCLUSIVE OF THE REPAIR OF INSULATOR HEAT S/TYRE HOUSING, SHIELD ASSY LH REAR SIDE, SHIELD ASSY REAR SIDE RH AND S/TYRE HOUSING.		3,900.00	2,340.00
	S/PAINT REAR PORTION, CHASIS FRAME, S/TYRE HOUSING AND LH / RH REAR PILLAR.		3,000.00	1,750.00
	R/I REAR WHEELHOUSE FINISHER, PILLAR FINISHER TO ASSIST REPAIR.		240.00	240.00
	DISCONNECT / CONNECT POWER SUPPLY.		240.00	240.00
	SUPPLY AND RENEW REAR NO PLATE (SMART PLATE WIT7H CASING) LONG. (NPA)	NOT NECESSARY	-	-
	CHECK LIGHTING.		48.00	48.00
	VACUUM LOOSE GLASS (REAR WINDSCREEN).		240.00	240.00
	(REPAIR LH / RH REAR PILLAR). (NPA)	NOT NECESSARY	-	-
	TRANSFER REAR TAIL MECHANICAL PARTS ON RENEW (TOP / BOTTOM).		240.00	240.00
	CHARGE AND DISCHARGE A/CON GAS. (ADDITIONAL)		120.00	120.00
			11,298.00	6,778.00
	<b>GRAND TOTAL</b>		<b>31,321.76</b>	<b>19,786.26</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>19,786.26</b>

Report Ref No. CS/EQI21001331/R1vd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

5-Feb-2021

INS/IC/LAW/0029/2021

EQ INSURANCE COMPANY LIMITED  
5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
Singapore 069110

Attn : Motor Claim Manager  
Claim Dept

Dear Sir

**SUPPLEMENTARY CLAIM**

REGN. NO. : SMQ6601H  
POLCY NO. : -

Further to our claim we are submitting a supplementary claim for the below mentioned items which were found damaged during the course of repairs.

<u>Replacement of Damaged Items</u>		
1	CHARGE AND DISCHARE A/CON GAS	\$120.00 ✓
2	FINISHER RH REAR WHEELHOUSE cra ✓	\$638.00 NETT
3	CARPET FLOOR de ✓	\$545.20 NETT
4	COOLING UNIT LH REAR cra ✓	\$900.00 S/NETT
5	COVER HIGH MTG 3RD BRAKE LIGHT GARNISH cut ✓	\$61.20 NETT

TOTAL \$ 2,264.40

We trust the above supplementary claim will meet with your kind approval and we will forward to you the final repair bill together with the satisfaction note on completion repairs.

Yours faithfully  
TAN CHONG MOTOR SALES PTE LTD

Lawrence Teo  
Insurance Claim Dept

Cc: Surveyor

slc

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	26/01/2021 15:40 (SGT)
Date of Accident	25/01/2021 16:40 (SGT)
Exact Location of Accident	Serangoon Rd, Singapore
Additional Location Information	ENTRANCE TO KWONG WAI SHIU HOSPITAL
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SMQ6601H

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	FUM YONG YUEN
NRIC No	SXXXX417F
Email Address	FUMFRANCIS@YAHOO.COM.SG
Mobile Phone No	(Phone) +65-90283096
Alternative Phone No	+65-90283096

#### VEHICLE PARTICULARS

Manufacturer	Nissan
Model	Serena
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire

#### INSURANCE COMPANY

Name of Insurance Company	NTUC
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5114191280-01
Cover Note Number	-

#### DRIVER

Name of Driver	FUM YONG YUEN
NRIC No	SXXXX417F
Date Of Birth	27/11/1969
Occupation	Outdoor

Driving Pass  
 experience  
 er  
 Site Number  
 Alt. Phone Number  
 Email Address  
 Address  
 Address complement  
 Postcode  
 Is the driver the policyholder?  
 If No, Relationship of the Driver with the Insured  
 Does Driver Own Other Vehicles?  
 Vehicle Registration Number of Other Vehicle Owned by Driver  
 Insurance Company of Other Vehicle Owned by Driver

26/02/1993  
 27 YEARS AND 11 MONTHS  
 Male  
 (Phone) +65-90283096  
 +65-90283096  
 FUMFRANCIS@YAHOO.COM.SG  
 BLK 792 WOODLANDS AVE 6 #13-691  
 -  
 730792  
 Yes  
 -  
 No  
 -  
 -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear  
 Weather Conditions Clear  
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No  
 Number of vehicles involved in the accident 2  
 Was anybody injured in the Accident? Yes  
 Was any injured conveyed to hospital by ambulance? No  
 Was any other material or property damaged? Yes  
 Number of Passengers (Including Driver) 2  
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

PASSENGER 1

Name MISS LOW  
 Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes  
 Police Station Name Traffic Police  
 Police Station Phone No (Phone) +65-65470000  
 Alt. Police Station Phone No (Fax) +65-65474900  
 Police Station Address 10 Ubi Avenue 3 Singapore 408865  
 Was notice of intended Prosecution given? No  
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO THE ATTACHED POLICE REPORT.

ATTACHMENT(S)

Are accident photos available for attachment? Yes  
 Was there any video captured by Car Camera? No  
 Was there any audio recorded? No

**DETAILS OF OTHER VEHICLE PROPERTY**

Vehicle Registration Number GBD4600Y  
 Vehicle Manufacturer Nissan  
 Vehicle Model Nv350  
 Vehicle Variant -



# LKK Auto Consultants Pte Ltd





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SMQ 6601H

## INSPECTION







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SMQ 6601H

## RE-INSPECTION





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

