

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21001332/APS3Q2
Date: 11/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SML1316R	Insured Vehicle No :	SDD121R
Date of Loss:	27/01/2021	Nature of Claim:	TP
		Claim No:	6504132816SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML1316R	Engine No:	G4FGKU147186
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMHD841CMKU910812
Reg. Date:	07/05/2019 (Man. Year: 2019)	Odometer:	55346 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,003.36	5,188.32	7,815.04	60.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	1,380.00	1,970.00	58.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,353.36	6,568.32	9,785.04	59.84
+ GST 7.00/7.00% (S\$)	1,144.74	459.78	684.96	59.84

Nett Amount (S\$)	17,498.10	7,028.10	10,470.00	59.84
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,735.55		
Global Sum Settlement (S\$)		7,730.00		

INSPECTION

Date of Assignment: 29/01/2021

Date Inspected: 29/01/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Cas Garage Pte Ltd (HQ)
No.1, Kaki Bukit Ave 6, #02-22 Autobay
Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	1,971.20 FL	*- FL
2	2		*FRONT BONNET HINGES	Not Necessary	291.20 FL	*- FL
3	1		*FRONT BONNET INSULATOR	Not Necessary	385.90 FL	*- FL
4	1		*FRONT BONNET LOCK	Not Necessary	235.90 FL	*- FL
5	4		*FRONT BONNET STOPPER	FRONT BONNET	34.40 FL	*- FL
6	2		*FRONT BONNET LABELLED	Not Necessary	56.00 FL	*- FL
7	1		*HEADLAMP RH	Cut	3,035.20 FL	*1,198.80 FL
8	1		*HEADLAMP BRACKET RH	Cracked	98.60 FL	*98.60 FL
9	1		*FRONT BUMPER	Distorted	658.20 FL	*474.00 FL
10	1		*FRONT BUMPER SIDE RETAINER	O/S Necessary	173.80 FL	*86.90 FL
11	1		*FRONT BUMPER TOP BRACKET RH	Cracked	98.60 FL	*98.60 FL
12	1		*FRONT BUMPER NUMBER PLATE GARNISH	Not Necessary	65.30 FL	*- FL
13	1		*FRONT BUMPER RADIATOR GRILLE	Cracked	1,218.60 FL	*628.60 FL
14	1		*FRONT BUMPER FRONT BUMPER SIGNAL LAMP	O/S Cracked	371.60 FL	*185.80 FL
15	1		*FRONT BUMPER SIDE STRIP	O/S Deformed	185.20 FL	*92.60 FL
16	1		*FRONT BUMPER SIDE COVER	O/S Cut	197.20 FL	*98.60 FL
17	1		*FRONT BUMPER LOWER LIP	Distorted	295.60 FL	*295.60 FL
18	1		*FRONT BUMPER TOP GARNISH RUBBER SEAL	Not Necessary	85.20 FL	*- FL
19	1		*FRONT BUMPER TOP GARNISH	Cracked	202.50 FL	*202.50 FL
20	1		*FRONT BUMPER AIR GUIDE	Cracked	125.80 FL	*125.80 FL
21	1		*FRONT ENGINE UNDER COVER	Cracked	356.80 FL	*356.80 FL
22	1		*FRONT BUMPER REINFORCEMENT	Bent	589.50 FL	*589.50 FL
23	1		*FRONT BUMPER REINFORCEMENT STRIFFENER	Cracked	175.20 FL	*175.20 FL
24	1		*FRONT BUMPER REINFORCEMENT SPONGE	Cracked	225.60 FL	*225.60 FL
25	1		*FRONT SUPPORT PANEL	Cracked	987.50 FL	*987.50 FL
26	1		*FRONT FENDER RH	Repair	1,227.70 FL	*- FL
27	1		*FRONT FENDER INNER COWLING RH	Torn	189.30 FL	*189.30 FL
28	1		*FRONT RESONATOR BOX	Not Necessary	158.30 FL	*- FL
29	1		*WIPER WASHER TANK	Deformed	125.80 FL	*125.80 FL
30	1		*WIPER WASHER TANK MOTOR	Not Necessary	89.50 FL	*- FL
31	1		*HORN	Not Necessary	80.30 FL	*- FL
32	1		*RADIATOR ASSY	Not Necessary	526.80 FL	*- FL
33	1		*RADIATOR FAN MOTOR W SPARE TANK	Not Necessary	652.60 FL	*- FL
34	1		*AC CONDENSER	Not Necessary	746.50 FL	*- FL
35	1		*SET FRONT NUMBER PLATE WITH CASING	Dented	50.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*SET FRONT BONNET INSULATOR CLIPS	Not Necessary	30.00 FS	*- FS
37	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
38	1		*SET FRONT BUMPER TOP GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
39	1		*SET FRONT ENGINE UNDER COVER CLIPS	Necessary	30.00 FS	*30.00 FS
40	1		*SET FRONT FENDER COWLING CLIPS	Not Necessary	30.00 FS	*- FS
41	1		*FRONT BUMPER TOP COVER	Missing	32.60 FL	*32.60 FL
42	1		*FRONT SUPPORT PANEL AIR GUIDE RH	Deformed	54.20 FL	*54.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,204.20	6,452.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,200.84	1,264.58
Total Parts (\$\$)	13,003.36	5,188.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT /STRAIGHTEN /REALIGN ACCIDENT AFFECTED PORTION	New	1,500.00	600.00
2	TO RESPRAY ACCIDENT AFFECTED PORTION	New	1,500.00	600.00
3	TO CONDUCT WIRING CHECK AND REPAIR	New	100.00	30.00
4	TO REMOVE /REFIT MECHANICAL PARTS TO ASSIST REPAIR AND TOP UP AC GAS	New	150.00	120.00
5	TO CONDUCT HEADLAMP ALIGNMENT	New	100.00	30.00
Gross Labour Cost (S\$)			3,350.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >