

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/EGI21001334/KVD3Q2

**Date:** 18/02/2021

### REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SHC5899E **Insured Vehicle No :** GBK5573Z

**Date of Loss:** 27/01/2021 **Nature of Claim:** TP **Claim No:** CDMCG21000186

### DESCRIPTION & IDENTIFICATION OF VEHICLE

<b>Reg No:</b>	<b>SHC5899E</b>		
<b>Make &amp; Model:</b>	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	<b>Engine No:</b>	2ZR2G96099
<b>Reg. Date:</b>	30/09/2020 (Man. Year: 2020)	<b>Chassis No:</b>	JTDKB3FU903092027
<b>Colour:</b>	Metallic Pearl White/Red	<b>Odometer:</b>	31661 km
<b>Engine Capacity:</b>	1798 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (\$\$):</b>	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

<b>General Condition:</b>	<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	Yes	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>

### CONDITION OF TYRES

<b>Front Tyre Size:</b>	195/65R15	<b>Rear Tyre Size:</b>	195/65R15
<b>Front Left Side:</b>	Sailun 9 mm	<b>Rear Left Side:</b>	Sailun 3 mm
<b>Front Right Side:</b>	Sailun 9 mm	<b>Rear Right Side:</b>	Sailun 3 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,478.57	889.40	4,589.17	83.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,400.00	665.00	4,735.00	87.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>10,878.57</b>	<b>1,554.40</b>	<b>9,324.17</b>	<b>85.71</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	761.50	108.81	652.69	85.71
<b>Nett Amount (\$\$)</b>	<b>11,640.07</b>	<b>1,663.21</b>	<b>9,976.86</b>	<b>85.71</b>

### INSPECTION

**Date of Assignment:** 28/01/2021

**Date Inspected:** 28/01/2021 **Inspected At:** Trans-Cab Services Pte Ltd (HQ)  
2 Ang Mo Kio Street 63  
Singapore 569111

**Estimated Period of Repair:** 2.0 days

**Adjuster:** KENNETH KONG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 18 Feb 2021)
<b>Parts:</b>	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC5899E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER,REAR BUMPER	Buckled	485.60 FL	*485.60 FL
2	1		*GUARD,REAR BUMPER,CENTER	Dented/Cut	374.50 FL	*374.50 FL
3	1		*REAR BUMPER TOWING COVER	Dented	22.00 FL	*22.00 FL
4	1		*SEAL,REAR BUMPER SIDE,RH	Serviceable	118.30 FL	*- FL
5	1		*RETAINER,REAR BUMPER SIDE,RH	Serviceable	132.60 FL	*- FL
6	1		*LENS & BODY REAR COMBINATION LAMP,RH	Serviceable	339.60 FL	*- FL
7	1		*LENS & BODY REAR COMBINATION LAMP,NO 2 RH	Serviceable	261.00 FL	*- FL
8	1		*REFLECTOR ASSY,REFLEX,RH	Serviceable	39.00 FL	*- FL
9	1		*PANEL SUB-ASSY,BACK DOOR	Repair	1,147.80 FL	*- FL
10	1		*GARNISH SUB-ASSY,BACK DOOR,OUTSIDE	Repair	913.60 FL	*- FL
11	1		*STAY ASSY,BACK DOOR,LH	Serviceable	242.50 FL	*- FL
12	1		*STAY ASSY,BACK DOOR,RH	Serviceable	242.50 FL	*- FL
13	1		*HINGE ASSY,BACK DOOR,LH	Repair	61.00 FL	*- FL
14	1		*HINGE ASSY,BACK DOOR,RH	Repair	61.00 FL	*- FL
15	1		*ORNAMENT SUB-ASSY,BACK DOOR	Necessary	47.90 FL	*47.90 FL
16	1		*PLATE LUGGAGE COMPARTMENT DOOR NAME,NO 2	Necessary	54.60 FL	*54.60 FL
17	1		*PLATE,BACK DOOR NAME,NO 1	Necessary	54.60 FL	*54.60 FL
18	1		*REAR BUMPER SIDE CLIP	Not Necessary	60.00 FS	*- FS
19	1		*REAR FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
20	1		*TAIL LAMP CLIP	Not Necessary	70.00 FS	*- FS
21	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
22	1		*SET REAR BUMPER CLIP	Necessary	85.00 FS	*50.00 FS
23	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS
24	1		*BUMPER CENTRE GUARD CLIP	Not Necessary	80.00 FS	*- FS
25	1		*REAR BOOT STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
26	1		*REAR BOOT STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
27	1		*REAR BUMPER PROTECTOR	No such part	180.00 FS	*- FS
28	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS
29	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
30	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
31	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)** **6,628.10** **1,149.20**  
**- List Item Discount on L Items 25.00/25.00% (\$\$)** **1,149.53** **259.80**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					<b>Total Parts (S\$)</b>	<b>5,478.57      889.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND REFIT REAR BIG & SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
2	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
4	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,600.00	200.00
5	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	400.00
7	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
8	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
9	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO REMOVE AND REFIT OF REAR FENDER FITTINGS,ATTACHMNET AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>5,400.00</b>	<b>665.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >