

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21001335/ETF3E2

Date: 15/02/2021

REFERENCE

Insured/Claimant:	LEOW KOK CHIEN	Policy No:	2100479160		
Date of Loss:	27/01/2021	Nature of Claim:	OD	Claim No:	6348787337SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF3854J		
Make & Model:	KIA FORTE K3, 1.6 (A)	Engine No:	G4FGGH623508
Reg. Date:	25/08/2016 (Man. Year: 2016)	Chassis No:	KNAFZ411MH5638347
Colour:	Blue	Odometer:	59045 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$51,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,311.60	2,864.00	1,447.60	33.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,590.00	2,780.00	2,810.00	50.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,901.60	5,644.00	4,257.60	43.00
+ GST 7.00/7.00% (S\$)	693.11	395.08	298.03	43.00
Nett Amount (S\$)	10,594.71	6,039.08	4,555.63	43.00

INSPECTION

Date of Assignment:	28/01/2021		
Date Inspected:	28/01/2021	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*PANEL ASSY-BACK	Dented	324.00 FL	*324.00 FL
3	1		*TRIM-TRANSVERSE RR	Crushed	58.00 FL	*58.00 FL
4	1		*PANEL ASSY-TRUNK LID	Dented	1,365.00 FL	*1,365.00 FL
5	1		*LOGO ASSY-KIA SUB	Necessary	37.00 FL	*37.00 FL
6	1		*EMBLEM-CERATO	Necessary	35.00 FL	*35.00 FL
7	1		*FORTE EMBLEM	Necessary	40.00 FL	*40.00 FL
8	1		*EMBLEM K3	Necessary	15.00 FL	*15.00 FL
9	1		*LATCH ASSY-TRUNK LID	Not Necessary	23.00 FL	*- FL
10	1		*STRIKER ASSY-TRUNK LID	Not Necessary	18.00 FL	*- FL
11	1		*W/STRIP-TRUNK LID OPNG	Torn	100.00 FL	*100.00 FL
12	1		*BRACKET-RR BUMPER SIDE MTG, LH	Not Necessary	29.00 FL	*- FL
13	1		*BRACKET-RR BUMPER SIDE MTG, RH	Not Necessary	29.00 FL	*- FL
14	1		*GUARD-BUMPER REAR RH	Not Necessary	17.00 FL	*- FL
15	1		*STAY-RR BUMPER LH	Bent	120.00 FL	*120.00 FL
16	1		*STAY-RR BUMPER RH	Bent	120.00 FL	*120.00 FL
17	1		*BRACKET-RR BEAM UPR MTG	Not Necessary	3.00 FL	*- FL
18	1		*BRACKET-RR BEAM UPR MTG, RH	Not Necessary	3.00 FL	*- FL
19	1		*BEAM-RR BUMPER	Broken	318.00 FL	*318.00 FL
20	2		*BRACKET-RR BEAM LWR MTG	Not Necessary	10.00 FL	*- FL
21	1		*BRACKET-RR BEAM LWR, CTR	Not Necessary	5.00 FL	*- FL
22	4		*RETAINER	Not Necessary	8.00 FL	*- FL
23	2		*RETAINER-BUMPER SIDE MTG	Not Necessary	2.00 FL	*- FL
24	10		*CLIP	Necessary	20.00 FL	*20.00 FL
25	1		*COVER-RR BUMPER	Dented	688.00 FL	*688.00 FL
26	1		*COVER-RR BUMPER, CTR	Cut	315.00 FL	*315.00 FL
27	1		*COVER-RR BPR UNDER	Not Necessary	42.00 FL	*- FL
28	1		*WIRING HARNESS-BWS EXT	Not Necessary	216.00 FL	*- FL
29	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	177.00 FL	*- FL
30	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	177.00 FL	*- FL
31	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	177.00 FL	*- FL
32	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	177.00 FL	*- FL
33	1		*SPOILER-RR	Not Necessary	590.00 FL	*- FL
34	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	69.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,377.00	3,575.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,065.40	711.00
Total Parts (\$\$)	4,311.60	2,864.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON REAR BOOT LID, REAR BUMPER, CUT / WELD REAR END PANEL, REPAIR REAR FLOOR PANEL	New	2,000.00	800.00
2	REMOVE AND INSTALL PARKING ASSIST	New	60.00	60.00
3	REMOVE AND INSTALL REAR SPOILER	New	80.00	80.00
4	REMOVE AND INSTALL REAR CABIN TO FACILITATE REPAIR WORK	New	120.00	120.00
5	PAINT WORK SPRAY REAR FLOOR PANEL, REAR END PANEL, REAR BOOT LID, REAR SPOILER, REAR BUMPER FACE AND AFFECTED PORTION	New	2,100.00	700.00
6	APPLY BODY SEALANT	New	120.00	40.00
7	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
8	PERFORM RUST PREVENTION	New	120.00	40.00
9	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
10	SUPPLY C & C LOGO	New	40.00	40.00
11	SUPPLY REAR NUMBER PLATE WITH FRAME	New	50.00	0.00
12	CUT, REPLACE & WELD REAR END PANEL (Supplementary)	New	400.00	400.00
13	SPRAY PAINT REAR END PANEL (Supplementary)	New	350.00	350.00
Gross Labour Cost (\$\$)			5,590.00	2,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >