

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001340/BBS3Q2
Date: 28/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900014090-01
Claimant Vehicle No :	SMS5787B	Insured Vehicle No :	SMJ239Y
Date of Loss:	27/01/2021	Nature of Claim:	TP
		Claim No:	7304627061SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS5787B		
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Engine No:	LEB7102248
Reg. Date:	02/03/2020 (Man. Year: 2018)	Chassis No:	GP72001615
Colour:	White	Odometer:	67191 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Davanti 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Davanti 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,954.56	5,470.16	6,484.40	54.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,030.00	1,960.00	2,070.00	51.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,984.56	7,430.16	8,554.40	53.52
Approved Total (Overridden) (S\$)		5,950.00		

(S\$)	15,984.56	5,950.00	10,034.56	62.78
+ GST 7.00/7.00% (S\$)	1,118.92	416.50	702.42	62.78
Nett Amount (S\$)	17,103.48	6,366.50	10,736.98	62.78
+ Loss of Use (9.0 x S\$80.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,093.95		
Global Sum Settlement (S\$)		7,000.00		

INSPECTION

Date of Assignment: 28/01/2021

Date Inspected: 29/01/2021

Estimated Period of Repair: 6.0 days

Inspected At:

160 SIN MING DRIVE #01-14

Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Adjuster: Lim Teow Guan**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,410.00 FL	*986.90 FL
2	1		*TAILGATE LOGO	Necessary	48.00 FL	*48.00 FL
3	1		*TAILGATE EMBLEM SHUTTLE	Necessary	110.00 FL	*46.60 FL
4	1		*TAILGATE EMBLEM HYBRID	Necessary	78.00 FL	*56.20 FL
5	1		*TAILGATE OUTER CHROME GARNISH	Not Damaged	471.00 FL	*- FL
6	1		*TAILGATE INNER LOCK	Jammed	258.70 FL	*167.10 FL
7	1		*TAILGATE INNER LOCK STRIKER	Not Damaged	65.00 FL	*- FL
8	1		*TAILGATE WEATHERSTRIP	Torn	215.00 FL	*168.50 FL
9	1		*TAILGATE INNER TRIMBOARD	Broken	476.80 FL	*426.00 FL
10	1		*TAILGATE INNER HANDLE GARNISH	Not Damaged	38.50 FL	*- FL
11	1		*TAILGATE WINDSCREEN MOULDING SIDE	Necessary	86.50 FL	*86.50 FL
12	1		*TAILGATE WINDSCREEN MOULDING TOP	Necessary	108.20 FL	*108.20 FL
13	1		*TAILGATE WINDSCREEN MOULDING BOTTOM	Necessary	108.20 FL	*108.20 FL
14	2		*TAILGATE LAMP	Broken	1,148.00 FL	*1,057.00 FL
15	2		*TAILGATE NUMBER PLATE LAMP	Not Damaged	97.20 FL	*- FL
16	1		*REAR BUMPER	Broken	890.00 FL	*783.70 FL
17	2		*REAR BUMPER RETAINER	Necessary	182.00 FL	*106.00 FL
18	2		*REAR BUMPER BRACKET	No such part	244.00 FL	*- FL
19	2		*REAR BUMPER REFLECTOR	Not Damaged	297.20 FL	*- FL
20	2		*REAR BUMPER REFLECTOR GARNISH	Not Damaged	651.20 FL	*- FL
21	1		*REAR BUMPER TOW CAP	Not Damaged	86.40 FL	*- FL
22	2		*REAR BUMPER INNER SIDE SPONGE	Not Damaged	117.20 FL	*- FL
23	1		*REAR LEYLESS CONTROL MODULE SENSOR	Not Damaged	398.60 FL	*- FL
24	1		*REAR FENDER INNER TRIM BOARD	Not Damaged	905.40 FL	*- FL
25	1		*REAR END PANEL CENTRE	Bent	685.20 FL	*685.20 FL
26	2		*REAR END PANEL SIDE	Not Damaged	731.60 FL	*- FL
27	1		*REAR END PANEL TOP GARNISH	Broken	177.00 FL	*155.70 FL
28	1		*SMART BUZZER	No such part	195.00 FL	*- FL
29	2		*TAILLAMP	Broken	1,563.00 FL	*1,160.40 FL
30	2		*TAILLAMP LOWER BRACKET	No such part	137.80 FL	*- FL
31	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
32	1		*TAILGATE SEALANT	Necessary	100.00 FS	*40.00 FS
33	1		*TAILGATE OUTER CHROME GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
34	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
35	1		*TAILGATE WINDSCREEN PRIMER AND CLEANER	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*50.00 FS
37	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*40.00 FS
38	1		*TAILGATE WINDSCREEN CLIPS	No such part	50.00 FS	*- FS
39	2		*TAILGATE LAMP CLIPS	Not Necessary	100.00 FS	*- FS
40	2		*TAILGATE LAMP SEAL	Not Necessary	120.00 FS	*- FS
41	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
42	1		*REVERSE CAMERA	Not Necessary	480.00 FS	*- FS
43	2		*REVERSE SENSOR	Scratched	500.00 FS	*200.00 FS
44	1		*REAR NUMBER PLATE W/CASING	Not Damaged	80.00 FS	*- FS
45	2		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	100.00 FS	*- FS
46	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
47	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
48	2		*TAILLAMP CLIPS	Necessary	100.00 FS	*60.00 FS
49	2		*TAILLAMP SEAL	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,350.70	6,700.20
- List Item Discount on L Items 20.00/20.00% (\$)	2,396.14	1,230.04
Total Parts (\$)	11,954.56	5,470.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R TAILGATE COMPONENT	New	150.00	70.00
2	R&R TAILGATE WINDSCREEN	New	250.00	120.00
3	R&R REVERSE SENSOR	New	150.00	60.00
4	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
5	UPHOLSTERY	New	300.00	0.00
6	CHECK WIRING	New	100.00	30.00
7	CONDUCT WATER LEAKAGE TEST	New	180.00	0.00
8	PANEL BEAT	New	1,200.00	800.00
9	RUST PROOFING	New	200.00	80.00
10	SPRAY PAINTING	New	1,200.00	800.00
Gross Labour Cost (S\$)			4,030.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >