



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 5785Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	DRL 5 LIGHT, LED+MODULE	CRUMPLED	1,446.08	1,446.08
1	FRONT AUX HEADLAMP FLASHER LH	CRUMPLED	904.40	904.40
1	BUMPER FRONT	TO REPAIR SEE LABOUR	1,868.80	-
1	FRONT FLAP	TO REPAIR SEE LABOUR	1,868.80	-
1	RETAINER:MALE&FEMALE, REAR LID, MAN BUS	SERVICEABLE	74.80	-
1	FRONT HEADLAMP LH	SCRATCHED	1,603.60	1,603.60
1	FRP HEADLAMP COVER LH (NS)	CRUMPLED	975.00	975.00
	LESS 10% DISCOUNT		-	-492.91
			8,741.48	4,436.17
<u>SPECIAL NETT ITEMS</u>				
1	STICKER SMRT (SN)	NECESSARY	75.00	75.00
			75.00	75.00
<u>LABOUR</u>				
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF BUMPER FRONT AND FRONT FLAP.		1,325.00	1,060.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		786.00	604.00
			2,111.00	1,664.00
GRAND TOTAL			10,927.48	6,175.17
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				4,950.00

Report Ref No. NS/INC21001345/Qqd3e2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.