

Kt

HENG YAP SENG AUTO SERVICES

Blk 160, Sin Ming Drive, #08-13 Sin Ming AutoCity, Singapore 575722

Hp : 9183 3008

Fax : 6873 2017

Vehicle No : GBH6724P
Vehicle Model : Toyota Hiace

Date : 01.02.2021

Not Authorised
11 Rep @ 5100h
Recovery After Rain
6 days

Estimate Repair Cost

No.	Qty	Parts List Items
1	1	Rear bumper
2	2	Rear bumper retainers
3	2	Rear bumper brackets
4	1 set	Rear bumper clips
5	1	Rear tailgate <i>1942.10</i>
6	1	Rear tailgate centre logo
7	1	Rear tailgate "HIACE" emblem
8	1	Rear tailgate lock
9	1	Rear tailgate number plate lamp
10	1	Rear tailgate brake lamp
11	1	Rear tailgate outer handle
12	1	Rear tailgate inner trim
13	2	Rear tailgate dampers
14	1	Rear tailgate weatherstrip
15	1	Rear windscreen glass <i>1115.70</i>
16	1	Rear windscreen moulding <i>130.50</i>
17	1	Rear wiper motor
18	1	Rear wiper arm
19	1	Roof top centre pillar (rear)
20	2	Taillamps <i>@ 365.10</i>
21	1	Rear end panel

258

\$ Bu	517.40	✓
\$ Sn	124.10	X
\$ Sn	110.35	X
\$ Sn	40.00	✓
\$ Bu	2,162.70	✓
\$ Sn	69.45	✓
\$ Sn	75.30	✓
\$ R	510.30	X
\$ Sn	69.40	X
\$ CM	220.00	✓
Warp Lpd	201.30	✓
\$ Sn	680.10	X
\$ Sn	598.80	X
\$ Sn	399.50	X
Shatter	1,301.35	✓
\$ Sn	210.10	✓
\$ Sn	509.10	✓
\$ Sn	95.30	X
mg cm	333.45	✓
ols cm	798.90	✓
\$ Bu	499.40	✓

Total \$ 9,526.30

Parts Special Nett Items

22	1	Rear number plate
23	1	Rear windscreen sealant
24	2	Reverse sensor

\$ Sn	60.00	X
\$ Sn	60.00	405n
\$ Sn	1,020.00	X
\$	1,140.00	

Total Parts \$ 10,666.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Labour

1	Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$ 1,500.00	800/
2	To putty and respray painting on affected areas.	\$ 1,300.00	800/
3	To remove, replace rear tailgate fittings to facilitate repair.	\$ 300.00	60/
4	To remove, replace rear windscreen glass.	\$ 250.00	120/
5	To remove, replace reverse sensor.	\$ 150.00	50/
6	To check wiring and lightings.	\$ 80.00	20/

Total Labour	\$ 3,580.00
--------------	-------------

Total Parts and Labour	\$ 14,246.30
------------------------	--------------