

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21001347/KTF3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001423923

Claimant
Vehicle No : GBH6724P

Insured Vehicle No : XB8017E

Date of Loss: 25/01/2021

Nature of Claim: TP

Claim No: 252592

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH6724P**

Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M)

Engine No: 1KD2805472

Reg. Date: 28/08/2018 (Man. Year: 2018)

Chassis No: JTFHT02P300244611

Colour: Silver

Odometer: 92442 km

Engine Capacity: 2982 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15X8

Rear Tyre Size:

195R15X8

Front Left Side: West Lake 8 mm

Rear Left Side:

West Lake 8 mm

Front Right Side: West Lake 8 mm

Rear Right Side:

West Lake 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,666.30	4,554.10	6,112.20	57.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	1,850.00	1,730.00	48.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,246.30	6,404.10	7,842.20	55.05
Approved Total (Overridden) (S\$)		5,100.00		
Nett Amount (S\$)	14,246.30	5,100.00	9,146.30	64.20

INSPECTION

Date of Assignment: 28/01/2021

Date Inspected: 29/01/2021 Inspected At:

Heng Yap Seng Auto Services - (sin Ming Drive) (HQ)
BLK 160 SIN MING DRIVE, #08-13
SIN MING AUTOCITY
Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Mar 2021)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH6724P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	517.40 F	*517.40 FL
2	2		*REAR BUMPER RETAINERS	Serviceable	124.10 F	*- FL
3	2		*REAR BUMPER BRACKETS	Serviceable	110.35 F	*- FL
4	1		*SET REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
5	1		*REAR TAILGATE	Bent	2,162.70 F	*1,942.10 FL
6	1		*REAR TAILGATE CENTRE LOGO	Necessary	69.45 F	*69.45 FL
7	1		*REAR TAILGATE HIACE EMBLEM	Necessary	75.30 F	*75.30 FL
8	1		*REAR TAILGATE LOCK	Repair	510.30 F	*- FL
9	1		*REAR TAILGATE NUMBER PLATE LAMP	Serviceable	69.40 F	*- FL
10	1		*REAR TAILGATE BRAKE LAMP	Cracked	220.00 F	*220.00 FL
11	1		*REAR TAILGATE OUTER HANDLE	Warped/Dented	201.30 F	*201.30 FL
12	1		*REAR TAILGATE INNER TRIM	Serviceable	680.10 F	*- FL
13	2		*REAR TAILGATE DAMPERS	Serviceable	598.80 F	*- FL
14	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	399.50 F	*- FL
15	1		*REAR WINDSCREEN GLASS	Shattered	1,301.35 F	*1,115.70 FL
16	1		*REAR WINDSCREEN MOULDING	Necessary	210.10 F	*130.50 FL
17	1		*REAR WIPER MOTOR	Jammed	509.10 F	*509.10 FL
18	1		*REAR WIPER ARM	Serviceable	95.30 F	*- FL
19	1		*ROOF TOP CENTRE PILLAR (REAR)	Mtg Cracked	333.45 F	*333.45 FL
20	1		*TAILLAMPS	O/s Cracked	798.90 F	*365.10 FL
21	1		*REAR END PANEL	Bent	499.40 F	*499.40 FL
22	1		*REAR NUMBER PLATE	Serviceable	60.00 FS	*- FS
23	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
24	2		*REVERSE SENSOR	Serviceable	1,020.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,666.30	6,058.80
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,504.70

Total Parts (\$\$)	10,666.30	4,554.10
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGE TO REMOVE,CUT OUT DAMAGE PORTION,JACK OUT,STRAIGHTEN,PANEL BEATING,WELDING,ALIGN AND RENEW REPLACED PARTS	New	1,500.00	800.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS	New	1,300.00	800.00
3	TO REMOVE,REPLACE REAR TAILGATE FITTINGS TO FACILITATE REPAIR	New	300.00	60.00
4	TO REMOVE,REPLACE REAR WINDSCREEN GLASS	New	250.00	120.00
5	TO REMOVE,REPLACE REVERSE SENSOR	New	150.00	50.00
6	TO CHECK WIRING AND LIGHTINGS	New	80.00	20.00
Gross Labour Cost (S\$)			3,580.00	1,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >