LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way, #09-16

Our File No:

CS/AIG21001350/EQF3E2

Singapore 079120

Date:

15/02/2021

REFERENCE

Date of Loss:

Insured/Claimant:

SEAH MIN FANN

22/01/2021

Policy No: 2100450598

OD

Claim No:

9330905178SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKZ6596R

KIA FORTE K3, 1.6 (A) Make & Model:

Engine No: G4FGFH600855

Reg. Date: 29/01/2016 (Man. Year: 2015) Colour: White

Chassis No: Odometer:

KNAFZ411MF5537893 71012 km

1591 cc **Engine Capacity:**

S\$49,000.00

Market Value/New Car Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Nature of Claim:

Footbrake (Serviceable): Yes

Yes

Handbrake (Serviceable):

Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

215/45Z R17 NFERA 5 mm NFERA 5 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 215/45Z R17 NFERA 5 mm

NFERA 5 mm

Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,314.00	3,331.20	982.80	22.78
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,210.00	1,700.00	1,510.00	47.04
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	7,524.00	5,031.20	2,492.80	33.13
	- Excess (S\$)	800.00	800.00	0.00	0.00
	(S\$)	6,724.00	4,231.20	2,492.80	37.07
	+ GST 7.00/7.00% (S\$)	470.68	296.18	174.50	37.07
	Nett Amount (S\$)	7,194.68	4,527.38	2,667.30	37.07

INSPECTION

Date of Assignment: 28/01/2021

Date Inspected: 28/01/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)

209 Pandan Gardens Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: **CHEN TSUE YEE** Manager: SHIAU CHAN

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY (NPA)	Not Necessary	0.00 F	*- FL
2	1		*COVER-FR BUMPER	Broken	728.00 F	*728.00 FL
3	1		*BRACKET-FR BUMPER SIDE MTG, LH	Broken	13.00 F	*13.00 FL
4	1		*PANEL-FENDER, LH	Dented	435.00 F	*435.00 FL
5	1		*GUARD ASSY-FRONT WHEEL, LH	Cut	109.00 F	*109.00 FL
6	1		*LAMP ASSY-HEAD, LH	Cut	1,870.00 F	*1,870.00 FL
7	1		*HUB ASSY-FR WHEEL	Not Necessary	150.00 F	*- FL
8	1		*WHEEL ASSY-ALUMINIUM	Cut	958.00 F	*958.00 FL
9	1	part. L=ListIte	*LOGO ASSY-KIA SUB	Necessary	51.00 F	*51.00 FL
1 -116	IIICIIISC	part. L-Listite	IIIDISC.	Sub Total (S\$)	4,314.00	4,164.00
			- List Item Disco	ount on L Items 0.00/20.00% (S\$)	0.00	832.80
				Total Parts (S\$)	4,314.00	3,331.20
			Report was unsubmitt	ed during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	RENEW FRT BUMPER, FRT FENDER LH	New	1,280.00	600.00
2	REMOVE & INSTALL PARKING SENSOR	New	100.00	100.00
3	SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH	New	1,100.00	700.00
4	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
5	TRANSFER FRT LEFT RIM	New	30.00	30.00
6	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TES HI-SCAN PRO TEST	T USING New	200.00	120.00
8	RENEW FRT UNDERCARRIAGE	New	350.00	0.00
	Gro	ss Labour Cost (S\$)	3,210.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >