5/13/22, 12:19 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21001355/KGA3Q2

Date: 13/05/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447

Claimant Vehicle SMR7378R Insured Vehicle No: SML5598S

No:

Date of Loss: 24/01/2021 Nature of Claim: TP Claim No: MFL2021D0001366

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMR7378R

Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 2NR5395377

Reg. Date: 31/10/2019 (Man. Year: 2019) Chassis No: MR2B23F3601190038

Colour: Metallic Black Odometer: 45904 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15
Front Left Side: Michelin 9 mm Rear Left Side: Michelin 9 mm
Front Right Side: Michelin 9 mm Rear Right Side: Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		444.30	0.00	444.30	100.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		700.00	540.00	160.00	22.86
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	1,144.30	540.00	604.30	52.81
	+ GST 7.00/7.00% (S\$)	80.10	37.80	42.30	52.81
	Nett Amount (S\$)	1,224.40	577.80	646.60	52.81
	+ Loss of Use (2.0 x S	\$100.00/day) (S\$)	200.00		
	+ Do	c/Search Fee (S\$)	8.00		
		Nett Liability (S\$)	785.80		

INSPECTION

Date of Assignment: 28/01/2021

Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 14/04/2021 Inspected At: Blk 1019 #01-374/382, Yishun Industrial Park A

Singapore 768761

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

5/13/22, 12:19 PM

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 May 2022)

Parts: 143 TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMR7378R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*REAR BUMPER	Repair	452.00 FL	*- FL
1		*REAR BUMPER RH SIDE RETAINER	Serviceable	122.90 FL	*- FL
5		*REAR BUMPER CLIP	Not Necessary	17.50 FL	*- FL
ınchise	part. L=ListIte	mDisc.	_		
			Sub Total (S\$)	592.40	0.00
- List Item Discount on L Items 25.00/25.00% (S\$)		148.10	0.00		
			Total Parts (S\$)	444.30	0.00
	1 1 5	-	1 *REAR BUMPER 1 *REAR BUMPER RH SIDE RETAINER 5 *REAR BUMPER CLIP anchise part. L=ListItemDisc.	1 *REAR BUMPER RH SIDE RETAINER Serviceable 5 *REAR BUMPER CLIP Not Necessary anchise part. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 25.00/25.00% (S\$)	1 *REAR BUMPER Repair 452.00 FL 1 *REAR BUMPER RH SIDE RETAINER Serviceable 122.90 FL 5 *REAR BUMPER CLIP Not Necessary 17.50 FL Inchise part. L=ListItemDisc. Sub Total (S\$) 592.40 - List Item Discount on L Items 25.00/25.00% (S\$) 148.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REMOVE & REFIX REAR BUMPER & ATTACHMENTS, PARKING SENSORS & TAILLAMP & PEALIGN THE SAME	New	300.00	180.00
2	PUTTY & RESPRAY PEAR BUMPER & PARKING SNESORS, REAR RH FENDER & ALL AFFECTED AREAS	New	400.00	360.00
	Gross Labour Cost (S\$)		700.00	540.00
	Report was unsubmitted during this p	orint-out.		

< END OF ESTIMATES >