

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001356/TEA3Q2**Date:** 08/03/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070122276
Claimant Vehicle No :	XD9291L	Insured Vehicle No :	SJZ1609H
Date of Loss:	27/11/2020	Nature of Claim:	TP
		Claim No:	4384760863SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XD9291L	Engine No:	11555219
Make & Model:	VOLVO FEE300, 7.1 64R (A)	Chassis No:	YV2VH70DXEB687497
Reg. Date:	24/07/2014 (Man. Year: 2014)	Odometer:	357736 km
Colour:	White		
Engine Capacity:	7146 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D)
Front Left Side:	Firenza 8 mm	Rear Left Side:	Firenza 8/8 mm
Front Right Side:	Firenza 8 mm	Rear Right Side:	Firenza 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,536.80	1,724.10	812.70	32.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	2,100.00	600.00	22.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,236.80	3,824.10	1,412.70	26.98
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	28/01/2021		
Date Inspected:	29/01/2021	Inspected At:	Sembwaste Senoko Depot (HQ) NO.20 ATTAP VALLEY ROAD Singapore 759909
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GRILLE	Cracked	210.50 FL	*210.50 FL
2	1		*GRILLE	Cracked	184.00 FL	*184.00 FL
3	1		*BUMPER	*Check	423.00 FL	*- FL
4	1		*BUMPER	Cracked	1,976.00 FL	*1,976.00 FL
5	1		*CORNER STEEL	Not Necessary	469.00 FL	*- FL
6	1		*BEZEL	Not Necessary	25.50 FL	*- FL
7	2		*NUT	Necessary	2.00 FL	*2.00 FL
8	1		*SPOILER	Torn	90.50 FL	*90.50 FL
9	1		*FRONT FOG LAMP	Not Necessary	243.50 FL	*- FL
					Sub Total (\$\$)	3,624.00
					- List Item Discount on L Items 30.00/30.00% (\$\$)	1,087.20
					Total Parts (\$\$)	2,536.80
						1,724.10

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE FRONT BUMPER GRILLE ,SPOILER LH BUMPER FOG LAMP & ACCESSORIES	New	900.00	600.00
2	TO RESPRAY WITH PRIMER & PAINT ON BUMPER & AFFECTED AREA	New	1,800.00	1,500.00
Gross Labour Cost (\$\$)			2,700.00	2,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >