

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21001357/AVF3E2

Date: 20/04/2021

REFERENCE

Insured/Claimant:	VENU MOTURU	Policy No:	1800142088		
Date of Loss:	26/01/2021	Nature of Claim:	OD	Claim No:	2427977025SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF8938G		
Make & Model:	AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A)	Engine No:	CZE846224
Reg. Date:	28/11/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V6K1004520
Colour:	Blue	Odometer:	36255 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$95,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,841.00	18,950.96	16,890.04	47.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,444.00	7,222.00	5,222.00	41.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	48,285.00	26,172.96	22,112.04	45.79
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	47,985.00	25,872.96	22,112.04	46.08
+ GST 7.00/7.00% (S\$)	3,358.95	1,811.11	1,547.84	46.08
Nett Amount (S\$)	51,343.95	27,684.07	23,659.88	46.08

INSPECTION

Date of Assignment:	28/01/2021		
Date Inspected:	28/01/2021	Inspected At:	24 Benoi Sector Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	9.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Distorted	1,987.00 FS	*1,589.60 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	2	*FRONT BUMPER GUIDE - LH / RH	Not Necessary	78.00 FS	*- FS
4	1	*FRONT BUMPER GRILLE - LOWER	Cracked	160.00 FS	*128.00 FS
5	1	*FRONT BUMPER CLOSING ELEMENT - LOWER	Not Necessary	536.00 FS	*- FS
6	2	*FRONT BUMPER CLOSING ELEMENT - LH / RH	Cracked	594.00 FS	*237.20 FS
7	2	*FRONT BUMPER COVER TRIM - LH / RH	Not Necessary	326.00 FS	*- FS
8	2	*FRONT BUMPER ADAPTER - LH / RH	Not Necessary	76.00 FS	*- FS
9	1	*RADIATOR GRILLE	Cracked	1,406.00 FS	*1,124.80 FS
10	1	*RADIATOR GRILLE CLOSING ELEMENT	Cracked	191.00 FS	*152.40 FS
11	1	*FRONT BUMPER AIR GRILLE - LH / RH	N/S Cracked	376.00 FS	*150.00 FS
12	1	*FRONT REINFORCEMENT BEAM	Bent	795.00 FS	*636.00 FS
13	1	*FRONT BUMPER FOAM FILLER	Cracked	189.00 FS	*151.20 FS
14	1	*FRONT BUMPER FOAM COVER	Deformed	122.00 FS	*97.20 FS
15	1	*STICKER FOR AIR CONDITIONER	Necessary	8.00 FS	*5.68 FS
16	1	*SIGN CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
17	2	*SIGNAL HORN - LH / RH	Not Necessary	400.00 FS	*- FS
18	2	*FRONT FENDER - LH / RH	Repair	1,702.00 FS	*- FS
19	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	72.00 FS	*- FS
20	1	*FRONT FENDER BRACKET - RH FRT	Not Necessary	39.00 FS	*- FS
21	1	*FRONT FENDER BRACKET - RH REAR	Not Necessary	28.00 FS	*- FS
22	1	*FRONT FENDER BRACE - RH	Not Necessary	96.00 FS	*- FS
23	10	*FRONT FENDER POP RIVET	Not Necessary	33.00 FS	*- FS
24	2	*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	338.00 FS	*- FS
25	1	*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	89.00 FS	*- FS
26	1	*BONNET	Dented	3,134.00 FS	*2,507.20 FS
27	1	*BONNET ATTACHMENT PARTS	Not Necessary	165.00 FS	*- FS
28	2	*BONNET HINGE - LH / RH	Bent	124.00 FS	*97.76 FS
29	1	*BONNET CATCH HOOK	Bent	90.00 FS	*50.32 FS
30	2	*BONNET SHOCK ABSORBER - LH / RH	Bent	220.00 FS	*175.20 FS
31	1	*BONNET EDGE PROTECTION	Necessary	28.00 FS	*22.00 FS
32	2	*BONNET LOCK - LH / RH	Damaged	427.00 FS	*341.60 FS
33	2	*BONNET HINGE COVER - LH / RH	Not Necessary	8.00 FS	*- FS
34	1	*BONNET BOWDEN CABLE	Jammed	58.00 FS	*46.00 FS
35	1	*BONNET LOCK CABLE	Not Necessary	74.00 FS	*- FS
36	1	*BONNET BOWDEN CABLE COVER	Not Necessary	10.00 FS	*- FS
37	1	*BONNET SOUND ABSORBER	Not Necessary	219.00 FS	*- FS
38	1	*PLENUM CHAMBER COVER	Not Necessary	179.00 FS	*- FS
39	2	*LED HEADLIGHT - LH / RH	N/S Cracked / O/S Cut	10,910.00 FS	*8,728.00 FS
40	1	*MAIN LIGHT POWER MODULE	Not Necessary	758.00 FS	*- FS
41	1	*LED WITH HEAT SINK	Not Necessary	733.00 FS	*- FS
42	1	*CONTROL UNIT FOR LIGHT CONTROL SYSTEM	Not Necessary	557.00 FS	*- FS
43	1	*HEADLIGHT HOSE - RH	Not Necessary	40.00 FS	*- FS
44	2	*HEADLIGHT WASHER CYLINDER - LH / RH	Not Necessary	284.00 FS	*- FS
45	1	*HEADLIGHT WASHER HOSE	Not Necessary	68.00 FS	*- FS
46	1	*WASH WATER RESERVOIR	Not Necessary	206.00 FS	*- FS
47	1	*FRONT LOCK CARRIER	Distorted	727.00 FS	*581.60 FS
48	1	*COOLANT	Necessary	179.00 FS	*143.04 FS
49	1	*A/C CONDENSER	Bent	529.00 FS	*422.80 FS
50	1	*REFRIGERANT LINE (CONDENSER>CUT OFF POINT)	Not Necessary	519.00 FS	*- FS
51	1	*REFRIGERANT LINE (COMPRESSOR>CONDENSER)	Not Necessary	475.00 FS	*- FS
52	1	*AIR COND PIPE BRACKET	Not Necessary	19.00 FS	*- FS
53	1	*ADDITIONAL RADIATOR	Bent	859.00 FS	*686.80 FS
54	1	*RADIATOR	Bent	951.00 FS	*760.40 FS
55	2	*RADIATOR BUSH - LOWER	Not Necessary	19.00 FS	*- FS

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
56	2	*RADIATOR BRACKET - UPPER	Not Necessary	82.00 FS	*- FS
57	2	*RADIATOR SEALING STRIP - LH / RH	Not Necessary	32.00 FS	*- FS
58	1	*RADIATOR FAN WITH FAN RING	Not Necessary	1,265.00 FS	*- FS
59	2	*RADIATOR AIR GUIDE - LH / RH	Cracked	50.00 FS	*38.88 FS
60	1	*RADIATOR SEAL - RH OUTER	Necessary	8.00 FS	*6.40 FS
61	1	*RADIATOR AIR GUIDE - UPPER CENTRE	Not Necessary	12.00 FS	*- FS
62	1	*INTAKE AIR DUCT COVER	Not Necessary	29.00 FS	*- FS
63	1	*INTAKE AIR GUIDE - LOWER	Not Necessary	56.00 FS	*- FS
64	1	*INTAKE AIR GUIDE - INNER	Not Necessary	20.00 FS	*- FS
65	1	*INTAKE AIR GUIDE HOSE	Not Necessary	34.00 FS	*- FS
66	1	*WATER DRAINAGE HOSE	Not Necessary	33.00 FS	*- FS
67	1	*INTAKE CONNECTION	Not Necessary	610.00 FS	*- FS
68	1	*INTAKE CONNECTION SEAL	Not Necessary	14.00 FS	*- FS
69	1	*CHARGE AIR COOLER	Not Necessary	775.00 FS	*- FS
70	1	*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
71	1	*SUNDRIES	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 35,841.00 18,950.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	280.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
3	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	500.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	2,750.00
5	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND BOTH FRONT FENDERS	New	4,000.00	2,300.00
6	TO RECOVER AND TOW BACK VEHICLE FROM SCENE OF ACCIDENT	New	280.00	0.00
7	TO CARRY OUT ORE / POST DIAGNOSTIC CHECK	New	384.00	192.00
Gross Labour Cost (\$\$)			12,444.00	7,222.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >