

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21001360/UPA3Q2**Date:** 17/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070120236
<b>Claimant Vehicle No :</b>	SMW7659D	<b>Insured Vehicle No :</b>	GBK5135E
Date of Loss:	26/01/2021	Nature of Claim:	TP
		Claim No:	8682972390SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMW7659D</b>		
Make & Model:	MERCEDES-BENZ A200, 1.3 AMG LINE (A)	Engine No:	28291480385328
Reg. Date:	09/12/2020 (Man. Year: 2020)	Chassis No:	W1K1770872J230417
Colour:	Grey	Odometer:	2831 km
Engine Capacity:	1332 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Continental 9 mm	Rear Left Side:	Continental 9 mm
Front Right Side:	Continental 9 mm	Rear Right Side:	Continental 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,073.00	3,044.61	3,028.39	49.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,895.00	500.00	1,395.00	73.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,968.00</b>	<b>3,544.61</b>	<b>4,423.39</b>	<b>55.51</b>
<b>+ GST 7.00/7.00% (S\$)</b>	557.76	248.12	309.64	55.51
<b>Nett Amount (S\$)</b>	<b>8,525.76</b>	<b>3,792.73</b>	<b>4,733.03</b>	<b>55.51</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment:	04/02/2021	
Date Inspected:	04/02/2021	Inspected At: Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26 Singapore 408711
Estimated Period of Repair:	2.0 days	

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY LH	Cracked	3,392.00 F	*3,044.61 F
2	1		*HEADLAMP LOWER BRACKET LH	Repair	702.00 F	*- F
3	1		*FRONT BUMPER FASCIA	Repair	1,617.00 F	*- F
4	1		*SET FRONT BUMPER CLIPS	Not Necessary	65.00 F	*- F
5	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	84.00 F	*- F
6	1		*FRONT BUMPER FOG LAMP COVER LH	Not Necessary	123.00 F	*- F
7	15		*FRONT GRILLE RIVET	Necessary	90.00 F	*- F
					<b>Total Parts (S\$)</b>	<b>6,073.00 3,044.61</b>

F=Franchise part.

Report was unsubmitted during this print-out.



Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CUT OUT RENEW KNOCKING & WELDING FRONT SUPPORT PANEL ,REMOVE & INSTALL ALL DAMAGE PARTS & RE-ALIGN BODY	New	780.00	200.00
2	SPRAY PAINTING ON DAMAGE PARTS	New	780.00	200.00
3	CHECK ALL LIGHTING AFTER REPAIRS }	New	35.00	100.00
4	DIAGNOSTIC & RESET }	New	300.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,895.00</b>	<b>500.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >