

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 199607	198R GST Reg. No. 19	9-96071	198-R	
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	ef:	CS/AGI21001362/Uqd3q2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate:	01/03/2021	
			C	ode:	AGI	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SLR 4468X	Veh. Inspected		SGM 2097G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10008861/KY	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		28/01/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA COROLLA ALTIS (A)	c.c		1598	
	Engine No.	HIDDEN	Year of Reg.		2006	
	Chassis No.	MR053ZEC107131407	Colour		SILVER	
	Odometer	283314 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	185/70 R14	TOURADOR		6 mm	
	L/H Front Tyre	185/70 R14	TOURADOR		6 mm	
	R/H Rear Tyre	185/70 R14	TOURADOR		6 mm	
	L/H Rear Tyre	185/70 R14	TOURADOR		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	27/01/2021	Inspection Date		28/01/2021	
	Survey held at	FASTECH AUTO PTE LTD				
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	D)III / IOOO IIDAIII	Estimate Days of Repair				
	Edilliato Dayo of Ropuli					

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: