

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21001363/UPA3Q2
Date: 08/11/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100480189
Claimant Vehicle No :	SLB8328A	Insured Vehicle No :	SLF3876X
Date of Loss:	26/01/2021	Nature of Claim:	TP
		Claim No:	1876764069SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB8328A	Engine No:	27492031655450
Make & Model:	MERCEDES-BENZ E200 AMG LINE, 2.0 (A)	Chassis No:	WDD2130422A547162
Reg. Date:	27/11/2019 (Man. Year: 2018)	Odometer:	40952 km
Colour:	Black		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R19	Rear Tyre Size:	275/35 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,830.40	2,909.70	920.70	24.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,390.00	850.00	540.00	38.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,220.40	3,759.70	1,460.70	27.98
Approved Total (Overridden) (S\$)		3,000.00		

Adjuster Report

	(S\$)	5,220.40	3,000.00	2,220.40	42.53
+ GST 7.00/7.00% (S\$)		365.43	210.00	155.43	42.53
Nett Amount (S\$)		5,585.83	3,210.00	2,375.83	42.53
+ Car Rental (3.0 x S\$140.00/day + 7.00% GST) (S\$)			449.40		
+ Doc/Search Fee (S\$)			2.00		
			Nett Liability (S\$)	3,661.40	
			Global Sum Settlement (S\$)	3,660.00	

INSPECTION

Date of Assignment: 28/01/2021

Date Inspected: 28/01/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,670.00 FL	*1,670.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	725.00 FL	*725.00 FL
3	1		*REAR BUMPER LOWER	Scratched	478.00 FL	*478.00 FL
4	1		*REAR BUMPER INNER FRAME	Cracked	105.00 FL	*105.00 FL
5	2		*REAR BUMPER PARKING SENSOR	Shorted (1 PCS ONLY)	510.00 FL	*255.00 FL
6	2		*REAR BUMPER PARKING SENSOR HOLDER	Not Necessary	30.00 FL	*- FL
7	1		*REAR BUMPER PARKING SENSOR WIRE HARNESS	Not Necessary	140.00 FL	*- FL
8	2		*REAR BUMPER SIDE RETAINER	Not Necessary	70.00 FL	*- FL
9	2		*REAR BUMPER SIDE HOLDER	Not Necessary	126.00 FL	*- FL
10	2		*REAR BUMPER BOTTOM BRACKET	Not Necessary	32.00 FL	*- FL
11	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	370.00 FL	*- FL
12	1		*REAR BUMPER DIFUSSION (NPA)	Not fitted	0.00 FL	*- FL
13	1		*BOOTLID (NPA)	Not Necessary	0.00 FL	*- FL
14	1		*BOOTLID LOCK (NPA)	Not Necessary	0.00 FL	*- FL
15	1		*BOOTLID WEATHERSTRIP (NPA)	Not Necessary	0.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,256.00	3,233.00
- List Item Discount on L Items 10.00/10.00% (S\$)	425.60	323.30
Total Parts (S\$)	3,830.40	2,909.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
2	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	180.00	50.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	500.00	380.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	500.00	400.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS	New	150.00	0.00
			Gross Labour Cost (S\$)	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >