



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2105679

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 12/08/2021
Reference CC6/CTI21001365/Ura3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLZ 9278C
Insured Veh. SMT 2127X
Claim No. SNM21D200545/LKKDS
Policy No. DMPCSNW00077852000
Accident Date 28/01/2021
Inspection Date 28/01/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21001365/Ura3q2 Date: 12/08/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMT 2127X	Veh. Inspected	SLZ 9278C	
Policy No.	DMPCSNW00077852000	Coverage (\$)	0.00	
Claim No.	SNM21D200545/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	28/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA HRV (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JHMRU1830GX203993	Colour	GREY	
Odometer	54902 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S & FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/01/2021	Inspection Date	28/01/2021	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 9278C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR WINDSCREEN MOULDING	NECESSARY	121.10	88.20
1	TAILGATE	BENT / WARPED	997.00	877.90
1	TAILGATE 'H' LOGO	NOT NECESSARY	35.80	-
1	TAILGATE 'HR-V' EMBLEM	NECESSARY	48.00	35.00
1	TAILGATE OUTER HANDLE GARNISH	NOT NECESSARY	399.20	-
2	TAILGATE REFLECTORS @\$388.50	N/S CRACKED	777.00	276.90
1	TAILGATE INNER LOCK	NOT NECESSARY	198.60	-
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	321.90	-
1	SET TAILGATE INNER TRIM BOARD CLIPS	NOT NECESSARY	50.00	-
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	188.20	-
1	REAR AIR VENT	TWISTED	66.80	66.80
1	REAR BUMPER	DISTORTED	766.80	463.70
2	REAR BUMPER SIDES @\$235.10	N/S DISTORTED	470.20	96.50
2	REAR BUMPER SIDE RETAINERS @\$35.00	N/S BENT	70.00	35.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	40.00
2	REAR BUMPER REFLECTORS @\$151.00	N/S CRACKED	302.00	151.00
1	REAR BUMPER LOWER DIFFUSER	DEFORMED / TWISTED	488.20	366.20
1	SET DEFORMED LOWER DIFFUSER CLIPS	NECESSARY	50.00	50.00
2	TAILLAMPS @\$489.00	N/S CRACKED	978.00	412.00
1	REAR END PANEL	BADLY DENTED	650.00	382.70
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	225.00	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,420.00	-
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	545.90	-
1	REAR FLOOR PANEL TOOLS SPONGE	NOT NECESSARY	665.20	-
2	REAR FENDERS @\$991.00	TO REPAIR SEE LABOUR	1,982.00	-
2	REAR FENDER INNER TRIM BOARDS @\$425.00	NOT NECESSARY	850.00	-
2	REAR FENDER OUTER PROTECTORS @\$280.20	N/S DISTORTED	560.40	180.20
2	REAR FENDER UNDER SHIELDS @\$188.00	N/S DISTORTED	376.00	175.50
1	REAR BUZZER	NOT NECESSARY	199.90	-

Report Ref No. CC6/CTI21001365/Ura3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR ANTENNA SENSOR	NOT NECESSARY	185.00	-
1	REAR EXHAUST	NOT NECESSARY	899.20	-
1	REAR EXHAUST HEAT SHIELD	NOT NECESSARY	188.00	-
1	REAR EXHAUST MOUNTING	NOT NECESSARY	58.00	-
1	BONNET	BUCKLED	1,100.90	821.70
2	BONNET HINGES @\$85.00	BENT	170.00	81.80
1	BONNET INSULATOR	DEFORMED / TORN	282.90	112.60
1	SET BONNET INSULATOR CLIPS	NECESSARY	50.00	50.00
1	BONNET INNER RUBBER	NECESSARY	52.80	52.80
1	BONNET LOCK	BENT	165.60	109.20
1	BONNET LOCK CABLE	JAMMED	188.20	166.20
1	FRONT BUMPER	DISTORTED	885.80	487.90
2	FRONT BUMPER SIDE RETAINERS @\$35.00	BENT	70.00	70.00
1	FRONT BUMPER CENTRE GRILLE	TORN	188.50	103.20
2	FRONT BUMPER FOG LAMP COVERS @\$155.00	TWISTED	310.00	290.00
2	FRONT BUMPER FOG LAMPS @\$399.00	CRACKED	798.00	491.80
1	FRONT BUMPER LOWER SPOILER	DISTORTED	520.00	365.30
1	FRONT BUMPER TOW COVER	DEFORMED	28.00	28.00
1	FRONT BUMPER UNDER COVER	NOT NECESSARY	288.90	-
1	FRONT BUMPER REINFORCEMENT	DISTORTED	388.90	228.80
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	40.00
1	FRONT GRILLE	CRACKED	485.80	366.20
1	FRONT GRILLE OUTER GARNISH	CRACKED	455.50	194.70
1	FRONT GRILLE 'H' LOGO	BROKEN	38.00	38.00
2	HEADLAMPS @\$1980.00	CRACKED	3,960.00	3,738.00
2	HEADLAMP LOWER BRACKETS @\$85.00	CRACKED	170.00	150.00
1	FRONT SUPPORT PANEL	BENT	745.11	486.20
1	FRONT SUPPORT PANEL TOP GARNISH	DISTORTED	410.80	265.30
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	NECESSARY	38.00	38.00
1	FRONT SUPPORT PANEL FRT BRACKET	CRACKED	166.00	145.80
2	FRONT FENDERS @\$615.00	TO REPAIR SEE LABOUR	1,230.00	-
2	FRONT FENDER INNER SHIELDS @\$181.00	NOT NECESSARY	362.00	-

Report Ref No. CC6/CTI21001365/Ura3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT FENDER INNER SHIELD CLIPS	NOT NECESSARY	50.00	-
2	FRONT FENDER OUTER PROTECTORS @\$288.00	DEFORMED / TORN	576.00	315.20
1	AIR CON CONDENSER	BENT /PUNCTURE	1,299.60	845.20
2	AIR CON CONDENSER SIDE GARNISH @\$98.00	TORN	196.00	196.00
1	HORN UNIT	NOT NECESSARY	88.70	-
1	RADIATOR	BENT / PUNCTURE	1,817.90	1,615.23
1	RADIATOR FAN COWLING	CRACKED	168.90	168.90
1	RADIATOR FAN BLADE	BENT	105.00	105.00
1	RADIATOR FAN MOTOR	JAMMED	450.00	305.00
1	AIR CON FAN COWLING	CRACKED	168.90	168.90
1	AIR CON FAN BLADE	BENT	105.00	105.00
1	AIR CON FAN MOTOR	JAMMED	450.00	305.00
1	AIR DUCT	NOT NECESSARY	164.80	-
1	ALTERNATOR	NOT NECESSARY	1,866.90	-
1	BATTERY TRAY	NOT NECESSARY	155.80	-
1	BATTERY BRACKET	NOT NECESSARY	121.00	-
1	AIR CLEANER BOX	NOT NECESSARY	622.80	-
1	DRIVER STEERING WHEEL BEARING	ACTIVATED	2,245.00	1,866.20
1	DRIVER STEERING WHEEL SPIRAL SENSOR	ACTIVATED	299.00	215.30
1	S.R.S CONTROL UNIT	ACTIVATED	1,550.00	860.20
1	PASSENGER AIR BAG	ACTIVATED	2,880.80	2,108.20
1	DASHBOARD	BUCKLED	1,500.00	1,066.30
1	S.R.S IMPACT SENSOR	ACTIVATED	228.00	185.30
2	FRONT SAFETY BELTS @\$750.00	ACTIVATED	1,500.00	990.00
1	FRONT WINDSCREEN	CRACKED	1,450.00	1,266.30
1	FRONT WINDSCREEN MOUDLING	NECESSARY	162.80	110.80
1	RADIATOR SPARE TANK	NOT NECESSARY	138.80	-
1	WIPER WASHER TANK	NOT NECESSARY	221.90	-
1	AIR CON SUCTION HOSE	NOT NECESSARY	311.80	-
1	AIR CON DISCHARGE HOSE	NOT NECESSARY	322.50	-
1	ABS PUMP	NOT NECESSARY	2,850.00	-
1	FRONT VIEW MIRROR	CRACKED	185.00	185.00
	LESS 20% DISCOUNT		-	-5,120.43

Report Ref No. CC6/CTI21001365/Ura3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
			53,036.01	20,481.70
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	50.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	200.00	-
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	SET FRONT WINDSCREEN SOLAR FILM (SN)	NECESSARY	280.00	200.00
1	FRONT WINDSCREEN INNER SEAL (SN)	NECESSARY	50.00	30.00
1	FRONT LICENCE PLATE (SN)	BENT	50.00	40.00
1	SET FRONT IN -CAR VIDEO CAM (SN)	BROKEN	480.00	350.00
1	BATTERY (SN)	NOT NECESSARY	200.00	-
			1,740.00	980.00
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	30.00
	TO DISMANTLE & REPLACED REVERSE SENSOR .		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO TRANSFER TAILGATE MECHANISM .		100.00	60.00
	TO SPRAY RUST PROOFING .		180.00	120.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY .		180.00	80.00
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REPLACE DASHBOARD .		380.00	250.00
	TO DISMANTLE & REPLACED AIR BAG SYSTEM.		500.00	280.00
	TO RESET & REPROGRAMME AIR BAG SYSTEM.		500.00	250.00
	TO DISMANTLE & REPLACED FRONT WINDSCREEN .		150.00	120.00
	TO REFILL AIR CON GAS.		120.00	100.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL ,REAR FENDERS AND FRONT FENDERS .		3,900.00	1,800.00
	TO PUTTY & SPRAY PAINTING .		2,800.00	1,800.00
			9,190.00	5,060.00
GRAND TOTAL			63,966.01	26,521.70

Report Ref No. CC6/CTI21001365/Ura3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			21,000.00
---	--	--	------------------

Report Ref No. CC6/CTI21001365/Ura3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLZ 9278C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLZ 9278C

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLZ 9278C

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

