

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21001367/R1BS3Q2

Date: 09/03/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SHB3773C	Insured Vehicle No :	SLV2126A
Date of Loss:	27/01/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000484

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB3773C		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEKU385603
Reg. Date:	14/11/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVLU183068
Colour:	Yellow	Odometer:	149187 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,052.50	289.84	1,762.66	85.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,710.00	500.00	1,210.00	70.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,762.50	789.84	2,972.66	79.01
+ GST 7.00/7.00% (S\$)	263.38	55.29	208.09	79.01
Nett Amount (S\$)	4,025.88	845.13	3,180.75	79.01
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	28/01/2021	
Date Inspected:	01/02/2021	Inspected At:
		Ding Auto Pte Ltd (corporation Road) (HQ) 31 Corporation Road Singapore 649825
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Mar 2021)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB3773C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	659.60 FL	*- FL
2	1		*REAR BUMPER CENTER GARNISH	Cracked	362.30 FL	*362.30 FL
3	1		*REAR BUMPER TOWING CAP	Not Necessary	38.60 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Serviceable	361.30 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Serviceable	146.30 FL	*- FL
6	1		*REAR FOG LAMP ASSY	Not Necessary	356.80 FL	*- FL
7	1		*REAR BUMPER RETAINER LH	Serviceable	78.22 FL	*- FL
8	1		*SET REAR BUMPER CLIP	Not Necessary	50.00 FS	*- FS
9	1		*REAR BUMPER RUBBER PROTECTOR PAD	Not Necessary	120.00 FS	*- FS
10	1		*SET REAR REVERSE SENSOR	Serviceable	230.00 FS	*- FS
11	1		*REPAIR REAR END PANEL (NPA)	Serviceable	0.00 FS	*- FS
12	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,453.12	362.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	400.62	72.46
Total Parts (\$\$)	2,052.50	289.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	STRAIGHT AND PANEL BEAT ACCIDENT AREA	New	550.00	200.00
2	DIAGNOSTIC (CLEAR FAULT CODE) & CHECK WIRING & LIGHTING SYSTEM	New	180.00	0.00
3	R&R REVERSE SENSOR	New	80.00	0.00
4	R&R SPARE TYRE TRAY & TRIM & SPARE TYRE & SPARE TYRE BOARD	New	150.00	0.00
5	RESPRAY REAR BUMPER	New	250.00	200.00
6	RESPRAY REAR BUMPER CENTER GARNISH	New	250.00	100.00
7	RESPRAY REAR END PANEL	New	250.00	0.00
Gross Labour Cost (\$\$)			1,710.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >