

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21001369/UGS3Q2
Date: 30/07/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900106645
Claimant Vehicle No :	SKL7634G	Insured Vehicle No :	SML8592M
Date of Loss:	27/01/2021	Nature of Claim:	TP
		Claim No:	7634675931SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL7634G	Engine No:	CHH015291
Make & Model:	VOLKSWAGEN GOLF GTI, 2.0 TSI (A)	Chassis No:	WVWZZZAUZEW108300
Reg. Date:	20/12/2013 (Man. Year: 2013)	Odometer:	98981 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,560.42	4,792.89	2,767.53	36.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	840.00	1,040.00	55.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,440.42	5,632.89	3,807.53	40.33
Approved Total (Overridden) (S\$)		4,500.00		

(S\$)	9,440.42	4,500.00	4,940.42	52.33
+ GST 7.00/7.00% (S\$)	660.83	315.00	345.83	52.33
Nett Amount (S\$)	10,101.25	4,815.00	5,286.25	52.33
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,137.00		

INSPECTION

Date of Assignment: 28/01/2021

Date Inspected: 28/01/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Torn	1,515.62 F	*1,076.45 FL
2	1		*FRONT BUMPER CENTRE GARNISH	Twisted	488.90 F	*225.43 FL
3	1		*FRONT BUMPER FOG LAMP GARNISH N/S	Serviceable	105.20 F	*- FL
4	1		*FRONT BUMPER PDC SENSOR N/S	Shorted	199.80 F	*199.80 FL
5	1		*FRONT BUMPER LICENCE PLATE GARNISH	Deformed	162.00 F	*105.00 FL
6	1		*FRONT BUMPER SPONGE	Torn	288.30 F	*148.22 FL
7	1		*FRONT BUMPER BEAM	Bent	650.00 F	*615.00 FL
8	1		*FRONT BUMPER NOZZLE SPRAY N/S	Cracked	399.20 F	*255.00 FL
9	1		*FRONT BUMPER SIDE RETAINER N/S	Not Necessary	66.50 F	*- FL
10	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
11	1		*HEADLAMP N/S	Cracked	2,820.00 F	*2,277.75 FL
12	1		*FRONT AIR CON SIDE GARNISH N/S	Torn	97.90 F	*92.50 FL
13	1		*FRONT SUPPORT PANEL	Repair	717.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	7,560.42	5,045.15
- List Item Discount on L Items 0.00/5.00% (S\$)	0.00	252.26
Total Parts (S\$)	7,560.42	4,792.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO RESET & REPROGRAMME SYSTEM	New	100.00	60.00
3	TO DISMANTLE & REPLACED FRT PDC SENSOR	New	80.00	50.00
4	TO SPRAY RUST PROOFING	New	50.00	0.00
5	TO REFILL AIR CON GAS	New	120.00	0.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	680.00	300.00
7	TO PUTTY & SPRAY PAINTING	New	800.00	400.00
Gross Labour Cost (S\$)			1,880.00	840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >