

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21001372/ABS3Q2
Date: 11/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SJR637A	Insured Vehicle No :	SGD1133P
Date of Loss:	10/01/2021	Nature of Claim:	TP
		Claim No:	6035464113SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR637A		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Engine No:	3ZZ4898567
Reg. Date:	08/06/2009 (Man. Year: 2009)	Chassis No:	MR053ZEE106147172
Colour:	Silver	Odometer:	51324 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	845.25	845.25	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,320.00	880.00	440.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,165.25	1,725.25	440.00	20.32
Approved Total (Overridden) (S\$)		1,350.00		

(S\$)	2,165.25	1,350.00	815.25	37.65
+ GST 7.00/7.00% (S\$)	151.57	94.50	57.07	37.65
Nett Amount (S\$)	2,316.82	1,444.50	872.32	37.65
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 27/01/2021

Date Inspected: 27/01/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Success United Pte Ltd (HQ)
 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
 Singapore 417921

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Dented	1,127.00 FL	*1,127.00 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	1,127.00
					- List Item Discount on L Items 25.00/25.00% (S\$)	281.75
					Total Parts (S\$)	845.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORK & WHERE CONSISTENT TO THE ACCIDENT	New	400.00	200.00
2	LABOUR TO TRANSFER DOOR GLASS ,DOOR COMPONENTS	New	120.00	80.00
3	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	800.00	600.00
Gross Labour Cost (S\$)			1,320.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >