

ASS. REC. BY:

REF:

CCG/CTA21001373/AP83

02

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: Smm7404A Yr Regn: 2015 / Oct.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Jazz C.C. 1498Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 77605 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMGK5850GX200983Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil S/Rim / STD A/Rim orTyre Size: F: 185/55R16R: 185/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 27/01/21

Survey held at

LeangDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Chuan

MV:

PV:

Nett:

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: _____

1)

☐

Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / L.B.F. (\$)

TP China.
Asker.
SMM 7404A.
Honda Jazz
JHMGK5850GX 200883.

Rear Bumper	Deformed.	493.70 ✓
Rear Bumper Clips.	Nec	30 ✓
Rear Bumper Side Holder x 02	Nec	$24.5 \times 2 = 49$ ✓
Rear Bumper Side Grille x 02	Nec	$48.5 \times 2 = 97$ ✓
Reverse Sensor :	Damaged	280(SW) ²⁰⁰ (SN)
Rear End Panel	Dented	393.50 ✓
Rear End Panel Top Garnish.	NN	75.80 +
Rear End Panel Sealant.	NEC	60(SW) ✓
Tailgate.	Repis	749.60. x
Jazz Emblem.	} Nec	32.50 ✓
RS Emblem.		45.40 ✓

Smm 7404A.

Panel Beating.

Spray Painting.

Wiring.

To remove reverse sensor

To remove upholstery.

~~800~~ 600

~~800~~ 700

~~50~~ 30

~~100~~ 50

~~150~~ * 40

List: 1044.50

less 20%: 835.60

S.N: 260

Labour: 1420

total: ~~25~~ 15.60

L/S: 12K

05 Days.