



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD  
8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:CHAN KIAN CHUAN

Ref: CC4/ASM21001374/Aga3q2  
Date: 26/10/2021  
Code: ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SHA 8510S	<b>Veh. Inspected</b>	SKC 4712G
<b>Policy No.</b>	P2419140	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S1M033Y4	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	28/01/2021

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HONDA JAZZ	<b>c.c</b>	1339
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2007
<b>Chassis No.</b>	JHMGD18507S221503	<b>Colour</b>	RED
<b>Odometer</b>	295635 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/55 R15	KAPSEN	6 mm
<b>L/H Front Tyre</b>	195/55 R15	KAPSEN	6 mm
<b>R/H Rear Tyre</b>	195/55 R15	KAPSEN	6 mm
<b>L/H Rear Tyre</b>	195/55 R15	KAPSEN	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	27/01/2021	<b>Inspection Date</b>	29/01/2021
<b>Survey held at</b>	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**