

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CS/AIG21001376/EVF3E2  
**Date:** 08/03/2021

### REFERENCE

Insured/Claimant: CHEN YOUSHENG Policy No: 2070119602  
Date of Loss: 27/01/2021 Nature of Claim: OD Claim No: 5717363114SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMV9968D**  
Make & Model: MITSUBISHI ECLIPSE CROSS, 1.5 (A) Engine No: 4B40HM5805  
Reg. Date: 09/09/2020 (Man. Year: 2019) Chassis No: JMAXTGK1WLZ001702  
Colour: Grey Odometer: 10358 km  
Engine Capacity: 1499 cc  
Market Value/New Car Price: S\$108,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18  
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm  
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,535.00	2,524.04	1,010.96	28.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,160.00	2,160.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,695.00</b>	<b>4,684.04</b>	<b>1,010.96</b>	<b>17.75</b>
<b>- Excess (S\$)</b>	<b>800.00</b>	<b>800.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>4,895.00</b>	<b>3,884.04</b>	<b>1,010.96</b>	<b>20.65</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>342.65</b>	<b>271.88</b>	<b>70.77</b>	<b>20.65</b>
<b>Nett Amount (S\$)</b>	<b>5,237.65</b>	<b>4,155.92</b>	<b>1,081.73</b>	<b>20.65</b>

### INSPECTION

Date of Assignment: 29/01/2021  
Date Inspected: 29/01/2021 Inspected At: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339  
Estimated Period of Repair: 4.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

*any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*MOULDING, FR WHEEL ARCH LH (NPA)	Missing	0.00 FS	*- FS
3	1		*HEADLAMP	Cut	1,020.00 F	*1,020.00 FL
4	1		*FACE, FR BUMPER	Broken	704.00 F	*704.00 FL
5	1		*BRKT, F/BMPR T/SIG LAMP, LH	Not Necessary	17.00 F	*- FL
6	1		*GARNISH, FR BUMPER SIDE	Missing	214.00 F	*214.00 FL
7	1		*BRACKET, FR BUMPER SIDE, LH	Broken	18.00 F	*18.00 FL
8	1		*INSULATOR, FR FENDER, LH	Not Necessary	52.00 F	*- FL
9	1		*FENDER, FR LH	Dented	599.00 F	*599.00 FL
10	1		*SHIELD, FR WHEELHOUSE, LH	Not Necessary	135.00 F	*- FL
11	1		*PNL, HEADLAMP SUPT, UPR LH	Not Necessary	59.00 F	*- FL
12	1		*LAMP A, T/SIG & FOG, FR LH	Cut	506.00 F	*506.00 FL
13	1		*MOULDING,FR WHEEL ARCH,LH (Supplementary)	Necessary	151.00 F	*151.00 FL
14	20		*CLIPS (Supplementary)	Necessary	40.00 F	*40.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,535.00</b>	<b>3,272.00</b>
<b>- List Item Discount on L Items 0.00/23.00% (\$\$)</b>	0.00	747.96
<b>Total Parts (\$\$)</b>	<b>3,535.00</b>	<b>2,524.04</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW FRT BUMPER, FRT FENDER LH	New	900.00	900.00
2	SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH	New	700.00	700.00
3	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	RESPRAY ON BONNET (Supplementary)	New	350.00	350.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,160.00</b>
				<b>2,160.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >