



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 4687G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET	DENTED / BENT	1,850.00	1,200.00
2	BONNET HINGES @\$125.00	NOT NECESSARY	250.00	-
1	BONNET LOCK	SERVICEABLE	215.00	-
1	FRONT GRILLE	TORN	880.00	660.00
1	FRONT GRILLE LOGO	NECESSARY	105.00	85.00
1	FRONT GRILLE TOP CHROME MOULDING	CRACKED	455.00	155.00
1	FRONT BUMPER	DISTORTED	1,280.00	1,250.00
1	FRONT BUMPER CENTRE GARNISH	DISTORTED	620.00	395.00
1	FRONT BUMPER CENTRE GRILLE	TORN	320.00	150.00
1	FRONT BUMPER LICENCE GARNISH	DISTORTED	150.00	80.00
1	FRONT BUMPER REINFORCEMENT	BENT	980.00	499.00
1	FRONT BUMPER FOG LAMP N/S	CRACKED	425.00	405.00
1	FRONT BUMPER FOG LAMP COVER N/S	NOT NECESSARY	65.00	-
2	FRONT BUMPER SIDE RETAINERS @\$85.00	NOT NECESSARY	170.00	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	1,020.00	-
2	HEADLAMPS @\$1800.00	CRACKED	3,600.00	2,300.00
1	AIR CON CONDENSER	NOT NECESSARY	1,125.00	-
1	INTER COOLER	NOT NECESSARY	1,480.00	-
1	FRONT LOWER PANEL	BENT	820.00	620.00
1	WIPER WASHER TANK	NOT NECESSARY	266.00	-
	LESS 10% DISCOUNT		-	-779.90
			16,076.00	7,019.10
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER LICENCE PLATE W/HOLDER (SN)	BROKEN	50.00	40.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
			100.00	90.00
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.		80.00	50.00

Report Ref No. CS/UOI21001382/Uqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REFILL AIR CON GAS.	NOT NECESSARY	120.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL. TO PUTTY & SPRAY PAINTING.		880.00	600.00
			1,500.00	800.00
			2,630.00	1,470.00
GRAND TOTAL			18,806.00	8,579.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,800.00

Report Ref No. CS/UOI21001382/Uqd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.