

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21001384/EVF3E2

Date: 15/02/2021

REFERENCE

Insured/Claimant:	TAN SEAH WAH	Policy No:	1700091158		
Date of Loss:	27/01/2021	Nature of Claim:	OD	Claim No:	4128448179SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV3578Y		
Make & Model:	KIA CERATO, 1.6 (A)	Engine No:	G4FGHH689059
Reg. Date:	28/12/2017 (Man. Year: 2017)	Chassis No:	KNAFX411MJ5757505
Colour:	Brown	Odometer:	61611 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$61,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,298.00	1,563.20	1,734.80	52.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,160.00	2,160.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,458.00	3,723.20	1,734.80	31.78
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	5,158.00	3,423.20	1,734.80	33.63
+ GST 7.00/7.00% (S\$)	361.06	239.62	121.44	33.63
Nett Amount (S\$)	5,519.06	3,662.82	1,856.24	33.63

INSPECTION

Date of Assignment:	29/01/2021		
Date Inspected:	29/01/2021	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*HUB ASSY-FR WHEEL	Not Necessary	150.00 F	*- FL
3	1		*BEARING-FRONT WHEEL HUB	Necesssary	131.00 F	*131.00 FL
4	1		*STRUT ASSY-FR, LH	Not Necessary	313.00 F	*- FL
5	1		*BEARING-STRUT	Not Necessary	54.00 F	*- FL
6	1		*GEAR ASSY-STEERING	Not Necessary	832.00 F	*- FL
7	1		*ARM COMPLETE-FR LWR, LH	Bent	380.00 F	*380.00 FL
8	1		*CROSSMEMBER COMPL (Supplementary)	Bent	1,330.00 F	*1,330.00 FL
9	1		*END ASSY-TIE ROD,LH (Supplementary)	Bent	88.00 F	*88.00 FL
					Sub Total (\$\$)	3,298.00
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00
					Total Parts (\$\$)	3,298.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR FRT BUMPER, FRT FENDER LH	New	400.00	400.00
2	SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH	New	700.00	700.00
3	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	RENEW FRT UNDER CARRIAGE	New	400.00	400.00
7	SUPPLY FRT LEFT RIM	New	360.00	360.00
8	TRANSFER FRT LEFT RIM	New	30.00	30.00
Gross Labour Cost (\$\$)			2,160.00	2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >