





TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

GAI Insured's Veh No : XE117L  
Date of Accident : 22 January 2021

Messrs Mopi Pte Ltd

Date : 23 January 2021

Estimate To Repair GBC1321C - Toyota DYNA 150 MANUAL 3SEATER  
Chassis No : JTFAT35Y10K201526

Ule  
Rev: 29/01/2021 1630h

| S/No | Quantity | Description                                                                                                             | Amount      |            |
|------|----------|-------------------------------------------------------------------------------------------------------------------------|-------------|------------|
|      |          | <u>LIST ITEMS</u>                                                                                                       |             |            |
| 01   | 1 pc     | front bumper                                                                                                            | \$ 700.00   | bt         |
| 02   | 1 pc     | n/s headlamp                                                                                                            | \$ 1,050.00 | 2m         |
| 03   | 1 pc     | n/s headlamp lower garnish                                                                                              | \$ 78.00    | x          |
| 04   | 1 pc     | n/s headlamp bracket                                                                                                    | \$ 65.00    | 7          |
| 05   | 1 pc     | front body panel                                                                                                        | \$ 1,195.00 | bt         |
| 06   | 1 pc     | front body panel "Dyna" badge                                                                                           | \$ 63.90    | nei        |
| 07   | 1 pc     | front body panel side garnish n/s -black                                                                                | \$ 55.00    | mis        |
| 08   | 1 pc     | front body panel top garnish - black                                                                                    | \$ 35.00    | ad         |
| 09   | 1 pc     | blower motor assy                                                                                                       | \$ 2,265.00 | x          |
| 10   | 1 pc     | n/s side mirror stay                                                                                                    | \$ 135.00   | bt         |
|      |          | Less 25 %                                                                                                               | \$ 5,641.90 |            |
|      |          |                                                                                                                         | \$ 1,410.48 |            |
|      |          |                                                                                                                         | \$ 4,231.42 |            |
|      |          | <u>LABOUR &amp; MISC. CHARGES</u>                                                                                       |             |            |
| 01   |          | To check electrical lighting concerned.                                                                                 | \$ 80.00    | 30         |
| 02   |          | To rust-proofing of the affected areas.                                                                                 | \$ 80.00    | 30         |
| 03   |          | To dismantle and refit instrument dashboard, check electrical lightings and re-run, re-route wire harness.              | \$ 250.00   | 180? photo |
| 04   |          | To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.                                       | \$ 200.00   | 100?       |
| 05   |          | To remove and refit front windscreen glass.                                                                             | \$ 120.00   | ?          |
| 06   |          | Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same. | \$ 800.00   | 600        |
| 07   |          | Putty and spray painting of the affected portion.                                                                       | \$ 800.00   | 600        |
|      |          |                                                                                                                         | \$ 2,330.00 |            |
|      |          | <b>Total</b>                                                                                                            | \$ 6,561.43 |            |

Tanfan 97495749  
WP 29/1/21 18430pm  
1/3 Resurvey after repair  
tanfan@lkkauto.com  
05-06 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Non-legal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: