

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21001386/QPA3Q2
Date: 09/12/2021

REFERENCE

| | | | |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 2070120551 |
| Claimant Vehicle No : | SG5769X | Insured Vehicle No : | SMU8018H |
| Date of Loss: | 15/01/2021 | Nature of Claim: | TP |
| | | Claim No: | 7143286770SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SG5769X | | |
| Make & Model: | MAN A95, 10.5 D (A) | Engine No: | 50343371984343 |
| Reg. Date: | 29/06/2016 (Man. Year: 2015) | Chassis No: | WMAA95ZZ4G7003240 |
| Colour: | Multi-colour | Odometer: | 352497 km |
| Engine Capacity: | 10518 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition: | | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size: | 275/70 R22.5 | Rear Tyre Size: | 275/70 R22.5 |
| Front Left Side: | Falken 6 mm | Rear Left Side: | Falken 6 mm |
| Front Right Side: | Falken 6 mm | Rear Right Side: | Falken 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 962.00 | 527.00 | 435.00 | 45.22 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 962.00 | 527.00 | 435.00 | 45.22 |
| + Loss of Use (1.0 x S\$300.00/day) (S\$) | | 300.00 | | |
| + Doc/Search Fee (S\$) | | 7.00 | | |

| | |
|------------------------------------|---------------|
| Nett Liability (S\$) | 834.00 |
| Global Sum Settlement (S\$) | 830.00 |

INSPECTION

Date of Assignment: 27/01/2021

Date Inspected: 27/01/2021

Estimated Period of Repair: 1.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Adjuster: OI SUN PIN**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|----------------------------|----------|------------|--------|
| <u>Labour Items</u> | | | | |
| 1 | TO REPAIR LH FRONT PORTION | New | 530.00 | 265.00 |
| 2 | TO PUTTY & RESPRAY | New | 432.00 | 262.00 |
| Gross Labour Cost (S\$) | | | 962.00 | 527.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >