

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 188C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER: FRONT, LH, FOR MB CITARO O530 (DISC 10%)	CRUMPLED	1,767.78	1,591.00
1	WINDSCREEN : FRONT, FOR MB CITARO O530 (DISC 10%)	CRACKED	3,887.85	3,499.07
1	STICKER SMRT (SN)	NECESSARY	75.00	75.00
1	PRIMER (SN)	NECESSARY	80.00	80.00
1	ACTIVATOR (SN)	NECESSARY	80.00	80.00
1	IU BRACKET (SN)	NECESSARY	35.00	35.00
10	ADHESIVE:DIRECT GLAZING @\$37.00 (SN)	NECESSARY	370.00	370.00
1	LAMP, BLINKER: FRONT, LEFT, FOR MB OC 500 LE	SERVICEABLE	155.30	-
1	FLAP: FRONT, CENTRE, FOR MB CITARO O530	TO REPAIR SEE LABOUR	1,513.05	-
			7,963.98	5,730.07
	<u>LABOUR</u>			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF FLAP: FRONT, CENTRE, FOR MB CITARO O530.		2,120.00	1,325.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		786.00	616.00
			2,906.00	1,941.00
	GRAND TOTAL		10,869.98	7,671.07
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			6,150.00

Report Ref No. NS/INC21001390/Qvf3e2


OI SUN PIN

Asst. Automotive Assessor


K.K.LAU CPT(RET)
**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**
REGD Auto Consultant-SAE, Licensed Appraiser
DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.