

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG21001391/UTF3Q2

**Date:** 01/03/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800142088

**Claimant**  
**Vehicle No :** SJG7294S **Insured Vehicle No :** SMF8938G

Date of Loss: 26/01/2021 Nature of Claim: TP Claim No: 2427977025SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |               |
|-----------------------------|-----------------------------------|-------------|---------------|
| Reg No:                     | <b>SJG7294S</b>                   |             |               |
| Make & Model:               | TOYOTA COROLLA, 1.5 X AXIO (A)    | Engine No:  | 1NZC396551    |
| Reg. Date:                  | 14/07/2008 (Man. Year: 2006)      | Chassis No: | NZE1416004010 |
| Colour:                     | Blue                              | Odometer:   | 256411 km     |
| Engine Capacity:            | 1496 cc                           |             |               |
| Market Value/New Car Price: | N/A                               |             |               |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |               |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |           |                  |             |
|-------------------|-----------|------------------|-------------|
| Front Tyre Size:  | 205/55R16 | Rear Tyre Size:  | 205/55R16   |
| Front Left Side:  | CST 5 mm  | Rear Left Side:  | Falken 5 mm |
| Front Right Side: | CST 5 mm  | Rear Right Side: | Falken 5 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 11,372.55         | 5,549.13          | 5,823.42          | 51.21         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 5,120.00          | 3,000.00          | 2,120.00          | 41.41         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>16,492.55</b>  | <b>8,549.13</b>   | <b>7,943.42</b>   | <b>48.16</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>6,800.00</b>   |                   |               |
| <b>(S\$)</b>                             | 16,492.55         | 6,800.00          | 9,692.55          | 58.77         |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 1,154.48          | 476.00            | 678.48            | 58.77         |
| <b>Nett Amount (S\$)</b>                 | <b>17,647.03</b>  | <b>7,276.00</b>   | <b>10,371.03</b>  | <b>58.77</b>  |

### INSPECTION

Date of Assignment: 29/01/2021

Date Inspected: 29/01/2021 Inspected At:

HANIP AUTOMOBILES  
ENGINEERING  
NO 1 KAKI BUKIT AVE 6 #01-73  
SINGAPORE 417883

Estimated Period of Repair: 8.0 days

**Adjuster:** MARCUS CHUA

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition              | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------------|------------------------|-------------|--------------|
| 1   | 1   |          | *BOOT LID                             | Buckled                | 1,645.80 FL | *1,045.10 FL |
| 2   | 1   |          | *BOOT LID INNER TRIM                  | Twisted/Torn           | 495.80 FL   | *311.20 FL   |
| 3   | 2   |          | *BOOT LID HINGES                      | Repair                 | 150.00 FL   | *- FL        |
| 4   | 1   |          | *BOOT LID LOWER CATCH                 | Not Necessary          | 42.00 FL    | *- FL        |
| 5   | 1   |          | *BOOT LID LOGO                        | Necessary              | 58.00 FL    | *58.00 FL    |
| 6   | 1   |          | *BOOT LID EMBLEM AXIO                 | Necessary              | 58.00 FL    | *58.00 FL    |
| 7   | 1   |          | *BOOT LID EMBLEM X                    | Necessary              | 45.00 FL    | *45.00 FL    |
| 8   | 1   |          | *BOOT LID OUTER MOULDING              | Bent/Cracked           | 285.00 FL   | *285.00 FL   |
| 9   | 2   |          | *REAR NUMBER PLATE LAMP               | Not Necessary          | 68.00 FL    | *- FL        |
| 10  | 1   |          | *REAR BUMPER                          | Distorted              | 1,209.00 FL | *522.01 FL   |
| 11  | 2   |          | *REAR BUMPER SIDE RETAINER            | Not Necessary          | 196.00 FL   | *- FL        |
| 12  | 2   |          | *REAR BUMPER DAMPERS                  | Cracked                | 170.00 FL   | *170.00 FL   |
| 13  | 2   |          | *TAILLAMP                             | Cracked                | 777.20 FL   | *777.20 FL   |
| 14  | 2   |          | *TAILLAMP LOWER BRACKET               | Cracked                | 196.00 FL   | *196.00 FL   |
| 15  | 2   |          | *TAILLAMP PANEL                       | Repair                 | 591.60 FL   | *- FL        |
| 16  | 1   |          | *REAR FENDER                          | O/s Buckled/N/s Repair | 1,890.00 FL | *945.00 FL   |
| 17  | 2   |          | *REAR FENDER INNER COWLING            | Not Necessary          | 190.00 FL   | *- FL        |
| 18  | 2   |          | *REAR FENDER INNER TRIM               | Distorted              | 790.00 FL   | *790.00 FL   |
| 19  | 2   |          | *REAR FENDER AIR VENT                 | Not Necessary          | 195.00 FL   | *- FL        |
| 20  | 1   |          | *REAR WINDSCREEN MOULDING             | Necessary              | 165.00 FL   | *165.00 FL   |
| 21  | 1   |          | *REAR SPARE TYRE BOLT                 | Not Necessary          | 38.00 FL    | *- FL        |
| 22  | 1   |          | *REAR END PANEL                       | Badly Dented           | 465.00 FL   | *465.00 FL   |
| 23  | 1   |          | *REAR END PANEL TOP GARNISH           | Twisted                | 195.00 FL   | *195.00 FL   |
| 24  | 1   |          | *REAR FLOOR PANEL                     | Repair                 | 767.00 FL   | *- FL        |
| 25  | 1   |          | *REAR FLOOR PANEL TOP BOARD           | Warped                 | 335.00 FL   | *335.00 FL   |
| 26  | 1   |          | *REAR TOOLS SPONGE                    | Not Necessary          | 198.00 FL   | *- FL        |
| 27  | 2   |          | *REAR CHASSIS MEMBER (NPA)            | Repair                 | 0.00 FL     | *- FL        |
| 28  | 1   |          | *BOOT LID LOCK                        | Twisted                | 235.00 FL   | *235.00 FL   |
| 29  | 1   |          | *BOOT LID WEATHERSTRIP                | Twisted                | 268.00 FL   | *268.00 FL   |
| 30  | 1   |          | *REAR EXHAUST MUFFLER                 | Repair                 | 845.00 FL   | *- FL        |
| 31  | 1   |          | *REAR NUMBER PLATE WITH CASING        | Cracked                | 60.00 FS    | *40.00 FS    |
| 32  | 1   |          | *SET REAR BUMPER CLIPS                | Necessary              | 60.00 FS    | *45.00 FS    |
| 33  | 1   |          | *SET BOOT LID INSULATOR CLIPS         | Necessary              | 50.00 FS    | *45.00 FS    |
| 34  | 2   |          | *TAILLAMP SEAL                        | Not Necessary          | 120.00 FS   | *- FS        |
| 35  | 1   |          | *REAR FENDER SEALANT                  | Not Necessary          | 80.00 FS    | *- FS        |
| 36  | 1   |          | *SET REAR FENDER COWLING CLIPS        | Not Necessary          | 50.00 FS    | *- FS        |
| 37  | 1   |          | *REAR WINDSCREEN SEALANT              | Necessary              | 80.00 FS    | *40.00 FS    |
| 38  | 1   |          | *REAR WINDSCREEN INNER SEAL           | Necessary              | 80.00 FS    | *30.00 FS    |
| 39  | 1   |          | *SET REAR END PANEL TOP GARNISH CLIPS | Not Necessary          | 50.00 FS    | *- FS        |
| 40  | 1   |          | *REAR FLOOR PANEL INSULATION SEAL     | Not Necessary          | 300.00 FS   | *- FS        |
| 41  | 1   |          | *BREAKDOWN TRIANGLE SIGN              | Not Necessary          | 120.00 FS   | *- FS        |
| 42  | 1   |          | *REVERSE CAMERA                       | Not Necessary          | 400.00 FS   | *- FS        |
| 43  | 1   |          | *SET REVERSE SENSOR                   | Shorted                | 250.00 FS   | *200.00 FS   |
| 44  | 1   |          | *REAR TYRE LH                         | Not Necessary          | 250.00 FS   | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                 |
|------------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>14,513.40</b> | <b>7,265.51</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | <b>3,140.85</b>  | <b>1,716.38</b> |
| <b>Total Parts (\$\$)</b>                                  | <b>11,372.55</b> | <b>5,549.13</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                                                          | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |                                                                                                                                      |          |                 |                 |
| 1                               | TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE DAMAGED BODYPARTS,REPAIR,ALIGN BODY STRUCTURE & DAMAGED AND WHERE CONSISTENT TO THE ACCIDENT | New      | 2,000.00        | 1,400.00        |
| 2                               | TO RESPRAY,PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT                                      | New      | 1,800.00        | 1,180.00        |
| 3                               | TO REMOVE,REINSTALL ELECTRICAL WIRING AND CHECK LIGHTING                                                                             | New      | 80.00           | 30.00           |
| 4                               | TO REMOVE AND REFIX REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING                                                           | New      | 80.00           | 50.00           |
| 5                               | TO REMOVE AND INSTALL REAR WINDSCREEN GLASS                                                                                          | New      | 150.00          | 120.00          |
| 6                               | TO REMOVE AND REFIT BOOT LID AND LOCK MECHANISM                                                                                      | New      | 180.00          | 60.00           |
| 7                               | TO REMOVE,REFIX AND REPLACE INTERIOR TRIMS,SEAT ASSY,FLOORBOARD CARPET AND ETC TO FACILITATE THE REPAIR                              | New      | 180.00          | 80.00           |
| 8                               | TO TUFF KOTE AND UNDERSEAL MATERIALS                                                                                                 | New      | 150.00          | 80.00           |
| 9                               | MOUNT WORK BENCH AND CHASSIS ALIGNMENT                                                                                               | New      | 500.00          | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                                      |          | <b>5,120.00</b> | <b>3,000.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >