LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21001393/R1VD3E2

Date: 08/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900019411

Claimant Vehicle VCACCAA

CROCK AND CR

No: Insured Vehicle No: GBC6132Z

Date of Loss: 02/01/2021 Nature of Claim: TP Claim No: 7999830818SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YP439M

 Make & Model:
 MITSUBISHI FUSO, 3.0 D FE83 (M)
 Engine No:
 4P10B90434

 Reg. Date:
 07/12/2015 (Man. Year: 2015)
 Chassis No:
 FEB21EA10703

 Colour:
 White
 Odometer:
 48733 km

Engine Capacity: 2998 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/85 R15 Rear Tyre Size: 195/85 R15 (D)
Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7/7 mm
Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/01/2021

Date Inspected: 29/01/2021 Inspected At: Ngee Ngee Motor Block K, No. 22 Pa

Block K, No. 22 Pandan Road

Singapore 128240

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRT BUMPER	Repair	0.00 F	*-F
2	1	*FRT PANEL	Repair	0.00 F	*-F
3	1	*FRT CORNER PANEL LH	Repair	0.00 F	*-F
4	1	*FRT SIGNAL LAMP LH	Cracked	0.00 F	*-F
F=Fra	anchise part.		Total Parts (S\$)	0.00	0.00
		Report was unsubm	itted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >