

## AUTOMOBILE ASSESSMENT REPORT

TO: NGIAN WEE TECK  
C/O: SKM GARAGE & TRADING LLP  
10 KAKI BUKIT ROAD 2,  
#03-31/32 FIRST EAST CENTRE,  
SINGAPORE 417868

Our Reference: 1120/SM718  
Date: 30-Nov-2020

**ASSESSMENT OF VEHICLE NO. SFN 4356 C**  
**DATE OF LOSS: 30-Oct-2020**

We have carried out a physical assessment at SKM GARAGE & TRADING LLP,  
10 Kaki Bukit Road 2, #03-31/32 First East Centre, Singapore 417868, according to your instruction  
on 04-Nov-2020 and are pleased to submit our report herewith.

### 1. VEHICLE PARTICULARS

Registration No.: SFN 4356 C  
Make & Model: MERCEDES BENZ C200 COUPE AME LINE (R18 LED)  
Year of Registration: 2017  
Engine Capacity: 1991  
Chassis No.: WDD2053422F489998  
Engine No.: 27492030769800  
Colour: WHITE  
Mileage (km): 56315

### 2. VEHICLE CONDITION

Body Paint: GOOD  
Steering: SERVICEABLE  
Foot Brake: SERVICEABLE  
Parking Brake: SERVICEABLE  
Modification: NIL

### 3. TYRE PARTICULARS & CONDITION

Front  
RH Make/Size/Thread: MICHELIN 245/35 R19 – 80%  
LH Make/Size/Thread: MICHELIN 245/35 R19 – 80%

Rear  
RH Make/Size/Thread: MICHELIN 275/30 R19 – 80%  
LH Make/Size/Thread: MICHELIN 275/30 R19 – 80%


#### 4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the FRONT portion.

#### 5. REMARKS

Market Value: Na  
Salvage Value: Na  
Repair Limit: Na

Estimated Amount: \$20,348.39  
Adjusted Amount: \$14,181.39  
Lump Sum: \$11,200.00  
Estimated Repair Days: 7 days



Pursuant to your instruction, we have **NOT AUTHORISED** repair.  
The assessment was conducted on a "Without Prejudice" basis.  
If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

#### Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

**ASSESSMENT REPORT FOR VEHICLE NO. SFN 4356 C**

**PARTS (LIST ITEMS)**

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	FRONT BONNET	Repair	2,155.00	-
1	FRONT 'AMG' GRILLE ASSY	Cracked	1,374.00	1,374.00 ✓
1	FRONT RH HEADLAMP	Repair	3,290.00	-
1	FRONT LH HEADLAMP	Cracked	3,290.00	3,290.00 ✓
1	FRONT LH HEADLAMP RUBBER SEAL	Necessary	SVC 42.00	42.00 ✗
1	FRONT BUMPER	Cracked	2,140.00	2,140.00 ✓
1	FRONT BUMPER ENERGY ABSORBER	Cracked	325.75	325.75 ✓
1	FRONT BUMPER UPPER FRAME	Cracked	155.00	155.00 ✓
1 ✓	FRONT BUMPER PARKING SENSOR	Cracked	282 ✓ 1,128.00	1,128.00
6	FRONT BUMPER PARKING SENSOR 'O' RING	Necessary	72.00	72.00 ✓
1	FRONT BUMPER PARKING SENSOR WIRE HARNESS	Cut	SVC 288.00	288.00 ✗
2	FRONT BUMPER SIDE RETAINER L/R	Bent	186.00	186.00 ✓
1	FRONT BUMPER TOW HOOK COVER	Necessary	SVC 74.00	74.00 ✗
1 ✓	FRONT BUMPER GRILLE L/R	Cracked	226.00	226.00 113 ✓
1 ✓	FRONT BUMPER GRILLE COVER L/R	Cracked	120 ✓ 240.00	240.00
1	FRONT BUMPER NUMBER PLATE GARNISH BRACKET	Cracked	131.00	131.00 ✓
1 ✓	FRONT BUMPER BRACKET L/R	Cracked	123.15 ✓ 446.31	446.31
1	FRONT BUMPER LOWER GRILLE	Cracked	182.00	182.00 ✓
1	FRONT BUMPER INNER FRAME GARNISH	Cracked	160.00	160.00 ✓
1 ✓	FRONT BUMPER INNER FRAME GARNISH BRACKET L/R	Bent	76 ✓ 152.00	152.00
1	FRONT BUMPER INNER SPONGE	Cracked	168.00	168.00 ✓
1	FRONT BUMPER REINFORCEMENT	Repair	421.00	-
2	FRONT BUMPER REINFORCEMENT BRACKET L/R	Repair	410.00	-
2	FRONT BUMPER REINFORCEMENT LOWER BRACKET L/R	Repair	254.00	-
1	FRONT BUMPER SUPPORT PANEL	Cracked	325.93	325.93 ✓
1	FRONT BUMPER LOWER COVER	Cracked	SVC 190.00	190.00 ✗
			17,825.99	11,295.99
Less 10% discount			1,782.60	1,129.60
Parts Total:			16,043.39	10,166.39

**ASSESSMENT REPORT FOR VEHICLE NO. SFN 4356 C**

**SPECIAL NETT ITEMS**

1	FRONT GRILLE CLIPS - SET	Necessary	50.00	20✓	50.00
1	FRONT BUMPER CLIPS - SET	Necessary	80.00	30✓	80.00
1	FRONT NUMBER PLATE	Bent	25.00		25.00✓
1	FRONT NUMBER PLATE HOLDER	Cracked	50.00		50.00✓
1	FRONT BUMPER 'BRABUS' CARBON LOWER LIP	Cracked	1,200.00	SVC	1,200.00✓
Special Nett Total :			1,405.00		1,405.00

**LABOUR**

S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	120.00	50✓ 100.00
2	To reset system after repair works.	500.00	300✓ 450.00
3	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,000.00	500 900.00
4	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,200.00	350 1,100.00
5	To apply anti-rust chemical on repaired and replaced panel.	80.00	30 60.00
Labour Total :		2,900.00	2,610.00
TOTAL (PARTS & LABOUR) \$		20,348.39	14,181.39

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

**\$11,200.00**

**(SINGAPORE DOLLARS ELEVEN THOUSAND TWO HUNDRED ONLY)**



Amas Ong  
Automobile Assessor

4 days



