

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21001397/QPA3Q2**Date:** 03/12/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070164204
Claimant Vehicle No :	SMB1425L	Insured Vehicle No :	SFA1778G
Date of Loss:	22/01/2021	Nature of Claim:	TP
		Claim No:	5301238076SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMB1425L		
Make & Model:	MAN NL320F (A22), 10.5 D ABS TURBO (A)	Engine No:	50337640243765
Reg. Date:	08/07/2014 (Man. Year: 2014)	Chassis No:	WMAA22ZZXE7002139
Colour:	Multi-colour	Odometer:	537647 km
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,027.20	960.00	2,067.20	68.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,768.00	1,068.00	700.00	39.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,795.20	2,028.00	2,767.20	57.71
+ Loss of Use (2.0 x S\$250.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		2,535.00		

INSPECTION

Date of Assignment:	29/01/2021	
Date Inspected:	28/01/2021	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

Adjuster: OI SUN PIN**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ,SIDE:L11 ,FOR MAN A22 BUS	Repair	1,092.50 F	*- F
2	1		*COVER :REAR TAIL LAMP ,LH,FOR MAN A22 BUS	Repair	974.70 F	*- F
3	1		*ADVERTISEMENT STICKER	Necessary	960.00 FS	*960.00 FS
					F=Franchise part. S=SpcNett.	
					Total Parts (S\$)	3,027.20 960.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,060.00	530.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	708.00	538.00
Gross Labour Cost (\$\$)			1,768.00	1,068.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >