

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21001399/EQF3E2

Date: 05/03/2021

REFERENCE

Insured/Claimant: Lim Lee Lai, Leslie (Lin Lilai, Leslie) Policy No: 1900119702
Date of Loss: 27/01/2021 Nature of Claim: OD Claim No: 6947960911SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMM8326K**
Make & Model: MITSUBISHI ECLIPSE CROSS, 1.5 (A) Engine No: 4B40GB9224
Reg. Date: 16/07/2019 (Man. Year: 2018) Chassis No: JMAXTGK1WJZ004785
Colour: Brown Odometer: 13090 km
Engine Capacity: 1499 cc
Market Value/New Car Price: S\$95,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,482.00	3,486.54	3,995.46	53.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,685.00	4,110.00	575.00	12.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,167.00	7,596.54	4,570.46	37.56
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	11,767.00	7,196.54	4,570.46	38.84
+ GST 7.00/7.00% (S\$)	823.69	503.76	319.93	38.84
Nett Amount (S\$)	12,590.69	7,700.30	4,890.39	38.84

INSPECTION

Date of Assignment: 29/01/2021

Date Inspected: 29/01/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*FACE, FR BUMPER	Broken	714.00 F	*714.00 FL
3	1		*COVER, FR BUMPER	Cut	200.00 F	*200.00 FL
4	1		*EXTENSION, FR BUMPER	Not Necessary	317.00 F	*- FL
5	1		*BRKT, F/BMPR T/SIG LAMP, LH	Broken	17.00 F	*17.00 FL
6	1		*GARNISH, FR BUMPER SIDE	Broken	214.00 F	*214.00 FL
7	1		*GARNISH, FR BUMPER SIDE	Broken	73.00 F	*73.00 FL
8	1		*BRACKET, FR BUMPER SIDE, LH	Broken	18.00 F	*18.00 FL
9	1		*BAR, FR BUMPER GUARD	Not Necessary	100.00 F	*- FL
10	1		*REINF, FR BUMPER SIDE, LH	Not Necessary	35.00 F	*- FL
11	1		*REINFORCEMENT, FR BUMPER	Not Necessary	552.00 F	*- FL
12	1		*GRILLE ASSY, RADIATOR	Not Necessary	445.00 F	*- FL
13	1		*COVER, FR BUMPER GRILLE	Not Necessary	302.00 F	*- FL
14	1		*HOOD	Dented	783.00 F	*783.00 FL
15	1		*LATCH, HOOD	Not Necessary	128.00 F	*- FL
16	1		*FENDER, FR LH	Dented	599.00 F	*599.00 FL
17	1		*SHIELD, FR WHEELHOUSE, LH	Not Necessary	135.00 F	*- FL
18	1		*PNL, HEADLAMP SUPT, UPR LH	Not Necessary	59.00 F	*- FL
19	1		*GARNISH, SIDE SILL, LH	Not Necessary	91.00 F	*- FL
20	1		*MOULDING, FR WHEEL ARCH, LH	Missing	151.00 F	*151.00 FL
21	1		*HEADLAMP ASSY, LH	Broken	967.00 F	*967.00 FL
22	1		*BRACKET, HEADLAMP	Not Necessary	16.00 F	*- FL
23	1		*BRACKET, HEADLAMP	Not Necessary	12.00 F	*- FL
24	1		*ARM ASSY, FR SUSP, LWR LH	Not Necessary	323.00 F	*- FL
25	1		*STRUT, FR SUSP, LH	Not Necessary	413.00 F	*- FL
26	1		*BEARING, FR SUSP STRUT	Not Necessary	32.00 F	*- FL
27	1		*LAMP A, T/SIG & FOG, FR LH (Supplementary)	Broken	506.00 F	*506.00 FL
28	1		*VALVE, TIRE (Supplementary)	Necessary	39.00 F	*39.00 FL
29	1		*HARNESS, FOG LAMP (Supplementary)	Broken	221.00 F	*221.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,482.00	4,522.00
- List Item Discount on L Items 0.00/23.00% (\$)	0.00	1,035.46
Total Parts (\$)	7,482.00	3,486.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, FRT FENDER LH, BONNET, FRT SUPPORT LH. REPAIR FRT WHEELHOUSING LH	New	1,350.00	1,350.00
2	SPRAY PAINTN FOR FRT BUMPER, BONNET, FRT FENDER LH, FRT SUPPORT LH FRT WHEELHOUSING LH	New	1,400.00	1,050.00
3	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	APPLY SEALANT FOR ACCIDENT PORTION	New	40.00	40.00
7	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
8	SUPPLY FRT LEFT RIM	New	480.00	480.00
9	TRANSFER FRT LEFT RIM	New	30.00	30.00
10	REPAIR FRT UNDER CARRIAGE	New	225.00	0.00
11	REPAIR LH WHEEL HOUSING & HEADLAMP SUPPORT (Supplementary)	New	225.00	225.00
12	SPRAY PAINT LH WHEEL HOUSING, HEADLAMP SUPPORT, RH FRONT FENDER AND LH WING MIRROR COVER (Supplementary)	New	605.00	605.00
Gross Labour Cost (\$\$)			4,685.00	4,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >