

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AXA16021914/T1PS3Q2-1**Date:** 09/03/2021REFERENCE

Handling Insurer: AXA Insurance Pte Ltd	Policy No:	P1399428
Claimant		
Vehicle No : XB9737D	Insured Vehicle No :	GBC5496E
Date of Loss: 30/08/2016	Nature of Claim:	TP
	Claim No:	C0398392

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XB9737D		
Make & Model:	mitsubishi FV517JD2RDEB, 11.9 D (M)	Engine No:	6D24364749
Reg. Date:	20/07/2005 (Man. Year: 2005)	Chassis No:	FV517PA00423
Colour:	Green	Odometer:	395662 km
Engine Capacity:	11945 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	10.00-20 (D)
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	ORNET 8/8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	ORNET 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,934.24	2,845.05	4,089.19	58.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,300.00	2,925.00	3,375.00	53.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,234.24	5,770.05	7,464.19	56.40
Approved Total (Overridden) (S\$)		4,600.00		
	(S\$)	13,234.24	4,600.00	8,634.24
	+ GST 7.00/7.00% (S\$)	926.40	322.00	604.40
	Nett Amount (S\$)	14,160.64	4,922.00	9,238.64
	+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00	
	+ Doc/Search Fee (S\$)		2.00	
	Nett Liability (S\$)		5,524.00	
	Global Sum Settlement (S\$)		5,500.00	

INSPECTION

Date of Assignment:	16/11/2016	
Date Inspected:	08/12/2016	Inspected At: Goldbell Engineering Pte Ltd ((Tuas)) No. 10 Tuas Avenue 18 Singapore 638894
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 03 Feb 2021)	
Parts:	N/A	mitsubishi FV517JD2RDEB 11.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XB9737D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE (CONSISTENT)	Serviceable	658.15 FL	*- FL
2	1		*FRONT BUMPER (CONSISTENT)	Bent	1,230.60 FL	*1,230.60 FL
3	1		*FRONT BUMPER STAY RHS (CONSISTENT)	Serviceable	386.51 FL	*- FL
4	2		*FRONT BUMPER STEP (CONSISTENT)	Cut 1pc Only	190.12 FL	*95.06 FL
5	1		*FRONT BUMPER SIDE GARNISH RHS (CONSISTENT)	Bent	178.45 FL	*178.45 FL
6	1		*FRONT BUMPER CENTRE GARNISH RHS (CONSISTENT)	Serviceable	158.52 FL	*- FL
7	1		*FOGLAMP BEZEL RHS (CONSISTENT)	Cut	64.55 FL	*64.55 FL
8	1		*HEADLAMP RHS (CONSISTENT)	Serviceable	514.19 FL	*- FL
9	1		*HEADLAMP BEZEL RHS (CONSISTENT)	Serviceable	308.00 FL	*- FL
10	1		*FRONT STEP GARNISH UPPER RHS (CONSISTENT)	Cracked	291.41 FL	*291.41 FL
11	1		*FRONT STEP GARNISH WALL RHS (CONSISTENT)	Serviceable	275.13 FL	*- FL
12	1		*FRONT STEP GARNISH LOWER RHS (CONSISTENT)	Serviceable	276.08 FL	*- FL
13	1		*FRONT STEP GARNISH LOWER COVER RHS (CONSISTENT)	Serviceable	229.87 FL	*- FL
14	1		*FRONT STEP PANEL RHS (CONSISTENT)	Serviceable	326.60 FL	*- FL
15	1		*TAIL LAMP LHS (CONSISTENT)	Serviceable	262.19 FL	*- FL
16	1		*TAIL LAMP RHS (CONSISTENT)	Serviceable	262.19 FL	*- FL
17	1		*REAR NUMBER PLATE LAMP (CONSISTENT)	Serviceable	65.93 FL	*- FL
18	1		*REAR CHASSIS CROSSMEMBER (CONSISTENT)	Not Necessary	500.50 FL	*- FL
19	1		*REAR BUMPER (CONSISTENT)	Bent	950.00 FS	*950.00 FS
20	1		*REAR BUMPER BRACKET LHS/RHS (CONSISTENT)	Serviceable	400.00 FS	*- FS
21	1		*REAR / FRONT NUMBER PLATE (CONSISTENT)	Front Bent	40.00 FS	*20.00 FS
22	1		*REAR STEP PANEL (CONSISTENT)	Bent	450.00 FS	*450.00 FS
23	1		*TAIL LAMP HOLDER LHS/RHS (CONSISTENT)	Serviceable	360.00 FS	*- FS
24	1		*YELLOW / BLACK STICKER (CONSISTENT)	Serviceable	20.00 FS	*- FS
25	1		*SUNDRIES (CONSISTENT)	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,478.99	3,310.07
- List Item Discount on L Items 25.00/25.00% (\$)	1,544.75	465.02
Total Parts (\$)	6,934.24	2,845.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	New	4,000.00	1,500.00
2	TO CHECK FOR & RECIFY WIRING FAULTS, ETC. TO CARRY OUT DIAGNOSTICS CHECK.	New	200.00	200.00
3	TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC.	New	2,100.00	1,225.00
			Gross Labour Cost (S\$)	2,925.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >