

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21001408/KGS3Q2
Date: 18/06/2021**REFERENCE**

| | | | |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 2070081370 |
| Claimant Vehicle No : | EV9983D | Insured Vehicle No : | SLC5619A |
| Date of Loss: | 27/01/2021 | Nature of Claim: | TP |
| | | Claim No: | 9530172019SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-------------------------------------|-------------|-------------------|
| Reg No: | EV9983D | Engine No: | FB16A826211 |
| Make & Model: | SUBARU LEVORG, 1.6 GT-S AWD CVT (A) | Chassis No: | JF1VM4K55GG002311 |
| Reg. Date: | 30/03/2016 (Man. Year: 2015) | Odometer: | 87817 km |
| Colour: | Metallic Pearl White | | |
| Engine Capacity: | 1600 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition: | | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 225/45 R18 | Rear Tyre Size: | 225/45 R18 |
| Front Left Side: | Dunlop 7 mm | Rear Left Side: | Dunlop 7 mm |
| Front Right Side: | Dunlop 7 mm | Rear Right Side: | Dunlop 7 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 1,886.55 | 1,728.00 | 158.55 | 8.40 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,640.00 | 530.00 | 1,110.00 | 67.68 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 3,526.55 | 2,258.00 | 1,268.55 | 35.97 |
| + GST 7.00/7.00% (S\$) | 246.86 | 158.06 | 88.80 | 35.97 |

| | | | | |
|---|-----------------|-----------------|-----------------|--------------|
| Nett Amount (S\$) | 3,773.41 | 2,416.06 | 1,357.35 | 35.97 |
| | | | | |
| + Loss of Use (3.0 x S\$60.00/day) (S\$) | | 180.00 | | |
| + Doc/Search Fee (S\$) | | 2.00 | | |
| | | | | |
| Nett Liability (S\$) | | 2,598.06 | | |

INSPECTION

Date of Assignment: 29/01/2021

Date Inspected: 29/01/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Optima Werkz Pte Ltd (HQ)
6 Kung Chong Road
Singapore 159143**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|----------------------------|---------------|-------------|--------------|
| 1 | 1 | | *Headlamp LH | Cut | 2,360.00 FL | *2,304.00 FL |
| 2 | 1 | | *HEADLAMP LOWER BRACKET LH | Serviceable | 55.40 FL | *- FL |
| 3 | 1 | | *FRONT BUMPER CLIPS | Not Necessary | 75.00 FS | *- FS |
| 4 | 1 | | *BONNET (NPA) | Repair | 0.00 FL | *- FL |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$) | 2,490.40 | 2,304.00 |
| - List Item Discount on L Items 25.00/25.00% (\$) | 603.85 | 576.00 |
| Total Parts (\$) | 1,886.55 | 1,728.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|---|----------|--------------------------------|-----------------|
| Labour Items | | | | |
| 1 | LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,& READJUST REAR ACCIDENT AREA } | New | 400.00 | 150.00 |
| 2 | LABOUR CHARGES TO REMOVE & REFIT FRONT BUMPER (INSTALLATION OF HEADLAMP)} | New | 120.00 | 0.00 |
| 3 | LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREA | New | 500.00 | 220.00 |
| 4 | TO CONDUCT HEADLAMP MODULE DECODING | New | 200.00 | 80.00 |
| 5 | TO CHECK WIRING & ELECTRICAL SYSTEM | New | 150.00 | 20.00 |
| 6 | TO DAIGNOSIS FAULT CODE & RESET MEMORY | New | 150.00 | 60.00 |
| 7 | TO TUFF KOTE & UNDERSEAL MATERIALS | New | 120.00 | 0.00 |
| | | | Gross Labour Cost (S\$) | 530.00 |
| | | | 1,640.00 | 1,640.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >