

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 158G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED / BUCKLED	1,150.60	1,150.60
1	REAR BUMPER RETAINER RHS	SERVICEABLE	38.20	-
1	REAR BUMPER RETAINER LHS	SERVICEABLE	38.20	-
1	REAR BUMPER REFLECTOR RHS	SERVICEABLE	85.80	-
1	REAR BUMPER SPONGE RHS	SERVICEABLE	95.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	598.70	-
1	TAILLAMP RHS	SERVICEABLE	698.70	-
	LESS 20% DISCOUNT		-541.04	-230.12
			2,164.16	920.48
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	SET REAR END PANEL CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET REAR END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
1	SET REVERSE SENSOR (SN)	SERVICEABLE	380.00	-
2	REVERSE SENSOR COVER @\$25.00 (SN)	SERVICEABLE	50.00	-
			580.00	50.00
	<u>LABOUR</u>			
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTION REPAIR PARTS, INCLUSIVE OF REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		800.00	200.00
	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT AFFECTED AREAS.		800.00	220.00
	TO REMOVE AND REFIT REVERSE SENSOR AND CONDUCT SAFE DISTANCE SETTING.		100.00	50.00
	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME.	NOT NECESSARY	100.00	-
	APPLY RUST PROOFING ON THE ADJACENT PANELS.	NOT NECESSARY	100.00	-
			1,900.00	470.00
	GRAND TOTAL		4,644.16	1,440.48

Report Ref No. CS/SMO21001410/Kvf3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS			1,440.48	
-----------------------------	--	--	----------	--

Report Ref No. CS/SMO21001410/Kvf3e2

KONG SENG CHEONG

Licensed Appraiser