

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21001413/T1QD3N2**Date:** 13/09/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00040262000

**Claimant Vehicle No :** SLW5617A **Insured Vehicle No :** YP7097U

Date of Loss: 28/01/2021 Nature of Claim: TP Claim No: SNM21D200556/C02/LOWCT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW5617A**

Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGJU136809

Reg. Date: 22/02/2018 (Man. Year: 2018) Chassis No: KMHD841CMJU630320

Colour: Grey Odometer: 128483 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	16,617.19	5,638.68	10,978.51	66.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,200.00	3,150.00	6,050.00	65.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>25,817.19</b>	<b>8,788.68</b>	<b>17,028.51</b>	<b>65.96</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,000.00</b>		
<b>(S\$)</b>	25,817.19	7,000.00	18,817.19	72.89
<b>+ GST 7.00/7.00% (S\$)</b>	1,807.20	490.00	1,317.20	72.89
<b>Nett Amount (S\$)</b>	<b>27,624.39</b>	<b>7,490.00</b>	<b>20,134.39</b>	<b>72.89</b>

INSPECTION

Date of Assignment: 29/01/2021

Date Inspected: 02/02/2021 Inspected At: AP Automotive Services Pte Ltd (HQ)  
Blk 9006 Tampines Street 93, #01-202  
Singapore 528840

Estimated Period of Repair: 7.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 Sep 2021)
<b>Parts:</b> 143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLW5617A)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,925.50 FL	*- FL
2	1		*BONNET LOCK	Not Necessary	141.30 FL	*- FL
3	1		*BONNET LOCK CATCH	Not Necessary	74.20 FL	*- FL
4	2		*BONNET HINGE SET	Not Necessary	137.40 FL	*- FL
5	2		*HEADLAMP LH & RH	Cut	2,396.20 FL	*2,396.20 FL
6	1		*HEADLAMP BRACKET LH	Cracked	34.00 FL	*34.00 FL
7	1		*FRONT BUMPER	Deformed	474.00 FL	*474.00 FL
8	1		*FRONT BUMPER FOG LAMP LH	Cracked	265.00 FL	*265.00 FL
9	1		*FRONT BUMPER SIDE LAMP LH	Cracked	174.00 FL	*174.00 FL
10	1		*FRONT BUMPER FOGLAMP GARNISH LH	Cracked	115.00 FL	*115.00 FL
11	1		*FRONT BUMPER INNER BRACKET LH	Not Necessary	28.00 FL	*- FL
12	1		*FRONT BUMPER RETAINER LH	Necessary	65.10 FL	*65.10 FL
13	1		*FRONT BUMPER REINFORCEMENT BAR	Not Necessary	695.90 FL	*- FL
14	1		*FRONT BUMPER BEAM (NPA)	Not Necessary	0.00 FL	*- FL
15	1		*FRONT BUMPER SPONGE	Cracked	121.75 FL	*121.75 FL
16	1		*FRONT BUMPER UNDERCOVER	Not Necessary	289.80 FL	*- FL
17	1		*FRONT FENDER L+R	N/s Bent/O/s Repair	2,454.00 FL	*1,227.00 FL
18	2		*FRONT FENDER COWLING L+R	O/s Missing/N/s Torn	351.30 FL	*351.30 FL
19	1		*FRONT SUPPORT PANEL	Not Necessary	967.12 FL	*- FL
20	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	86.25 FL	*- FL
21	1		*WIPER WASHER TANK	Not Necessary	151.87 FL	*- FL
22	1		*A PILLAR LH (NPA)	Repair	0.00 FL	*- FL
23	2		*FRONT DOOR L+R	Repair	2,763.00 FL	*- FL
24	1		*FRONT DOOR SIDE MIRROR ASSY L+R	N/s Cracked/O/S Not Necessary	763.60 FL	*381.80 FL
25	1		*FRONT DOOR SIDE MIRROR COVER L+R	N/s Cracked/O/S Not Necessary	262.40 FL	*131.20 FL
26	1		*FRONT DOOR LOCK LH	Not Necessary	211.85 FL	*- FL
27	1		*FRONT DOOR LOCK CATCH LH	Not Necessary	42.50 FL	*- FL
28	1		*FRONT DOOR WEATHERSTRIP LH	Not Necessary	131.75 FL	*- FL
29	2		*REAR DOOR L+R (NPA)	Repair	0.00 FL	*- FL
30	1		*REAR FENDER (RH)(NPA)	Repair	0.00 FL	*- FL
31	1		*REAR FENDER COWLING RH	Not Necessary	175.65 FL	*- FL
32	1		*TAIL LAMP RH	Not Necessary	1,094.70 FL	*- FL
33	1		*REAR BUMPER	Repair	810.90 FL	*- FL
34	1		*REAR BUMPER RETAINER LH	Not Necessary	72.95 FL	*- FL
35	1		*FRONT ABSORBER LH	Not Necessary	372.00 FL	*- FL
36	1		*FRONT LOWER ARM LH	Not Necessary	295.00 FL	*- FL
37	1		*FRONT KNUCKLE LH	Bent	363.00 FL	*363.00 FL
38	1		*FRONT KNUCKLE BEARING LH	Bent	398.00 FL	*195.00 FL
39	1		*FRONT RIM LH	Cut	691.50 FL	*691.50 FL
40	1		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
41	1		*FRONT FENDER COWLING CLIPS	Necessary	100.00 FS	*20.00 FS
42	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
43	1		*FRONT TYRE LH	Not Necessary	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 20,496.49 7,035.85****- List Item Discount on L Items 20.00/20.00% (\$\$) 3,879.30 1,397.17**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
<b>Total Parts (S\$)</b>						<b>16,617.19</b>	<b>5,638.68</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ON AFFECTED AREAS	New	2,800.00	1,200.00
2	SPRAY PAINT ON AFFECTED AREAS	New	2,600.00	1,600.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	New	150.00	30.00
4	TO CHECK WIRING AND FOG LAMP FUNCTION	New	150.00	0.00
5	TO CHECK WIRING AND SIDE LAMP FUNCTION	New	150.00	0.00
6	TO CHECK WIRING AND TAILLAMP FUNCTION	New	150.00	0.00
7	TO RNR FRONT DOOR SIDE MIRROR	New	300.00	40.00
8	TO RNR FRONT AND REAR DOOR MECHANISM	New	600.00	0.00
9	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	80.00
10	TO RNR UNDERCARRIAGE	New	250.00	100.00
11	TO CHECK WHEEL BALANCING	New	250.00	50.00
12	TO RNR INNER TRIM AND UPHOLSTERY	New	400.00	0.00
13	TO CHECK WATER LEAK	New	150.00	0.00
14	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
15	TO PERFORM RUST PROOFING	New	400.00	50.00
			<b>Gross Labour Cost (S\$)</b>	<b>9,200.00</b>
				<b>3,150.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >