

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21001417/EQF3E2

Date: 22/02/2021

REFERENCE

Insured/Claimant:	LAU YIH CHIA	Policy No:	1900009630		
Date of Loss:	08/01/2021	Nature of Claim:	OD	Claim No:	7791276132SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH4856A		
Make & Model:	KIA CERATO, 1.6 (A)	Engine No:	G4FGJH714180
Reg. Date:	25/01/2019 (Man. Year: 2018)	Chassis No:	KNAF3416MK5025338
Colour:	White	Odometer:	70272 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$73,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 5 mm	Rear Left Side:	Nexen 5 mm
Front Right Side:	Nexen 5 mm	Rear Right Side:	Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,457.20	918.40	1,538.80	62.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	950.00	750.00	44.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,157.20	1,868.40	2,288.80	55.06
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	3,857.20	1,568.40	2,288.80	59.34
+ GST 7.00/7.00% (S\$)	270.00	109.79	160.21	59.34
Nett Amount (S\$)	4,127.20	1,678.19	2,449.01	59.34

INSPECTION

Date of Assignment:	29/01/2021		
Date Inspected:	01/02/2021	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days		

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*LAMP ASSY-HEAD, LH	Not Necessary	1,219.00 FL	*- FL
3	1		*HORN ASSY-LOW PITCH	Not Necessary	74.00 FL	*- FL
4	1		*COVER-FR BUMPER	Broken	633.00 FL	*633.00 FL
5	1		*GRILLE-FRONT BUMPER	Not Necessary	262.00 FL	*- FL
6	1		*GRILLE ASSY-RADIATOR	Cracked	328.00 FL	*328.00 FL
7	1		*GARNISH-RADIATOR GRILLE	Not Necessary	38.00 FL	*- FL
8	1		*MOULDING-FRONT BUMPER, LH	Cut	36.00 FL	*36.00 FL
9	1		*LAMP ASSY-SIDE REPEATER, LH	Not Necessary	143.00 FL	*- FL
10	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 FL	*84.00 FL
11	1		*AIR DUCT-FR BUMPER, LH	Not Necessary	14.00 FL	*- FL
12	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
13	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
14	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
15	10		*CLIP (Supplementary)	Necessary	10.00 FL	*10.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	3,059.00 1,143.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	601.80 224.60
					Total Parts (\$\$)	2,457.20 918.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER PANEL & AFFECTED AREA	New	800.00	400.00
2	PAINT WORK ON FRT BUMPER PANEL	New	700.00	350.00
3	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
5	TO SUPPLY FRT NUMBER PLATE WITH FRAME	New	50.00	50.00
Gross Labour Cost (\$\$)			1,700.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >