

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001425/EPA3Q2**Date:** 08/06/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMU8839E**Insured Vehicle No :** GBK365R

Date of Loss: 26/01/2021

Nature of Claim: TP Claim No: 1853153735SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMU8839E**

Make & Model: TOYOTA COROLLA, AXIO 1.5 X (A)

Engine No: 1NZC996939

Reg. Date: 28/05/2008 (Man. Year: 2008)

Chassis No: NZE1416076382

Colour: Blue

Odometer: 296925 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R14

Rear Tyre Size: 185/60R14

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,990.00	1,140.00	1,850.00	61.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,000.00	1,550.00	3,450.00	69.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,990.00	2,690.00	5,300.00	66.33
Approved Total (Overridden) (S\$)		2,150.00		
Nett Amount (S\$)	7,990.00	2,150.00	5,840.00	73.09
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 29/01/2021

Date Inspected: 29/01/2021 Inspected At:

Auburn Auto Pte Ltd (HQ)
176 SIN MING DRIVE, #04-18 SIN MING
AUTOCARE
Singapore 575721

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER CLIP REAR	Necessary	150.00 F	*30.00 FL
2	1		*BUMPER REAR	Crushed	545.00 F	*545.00 FL
3	1		*RIGHT SIDE FENDER	Dented	945.00 F	*945.00 FL
4	1		*CONDENSER	Not Necessary	450.00 F	*- FL
5	1		*RADIATOR	Not Necessary	450.00 F	*- FL
6	1		*REINFORCEMENT BAR SPONGE	Not Necessary	450.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,990.00	1,520.00
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	380.00
Total Parts (S\$)	2,990.00	1,140.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECKING OF WIRING,LIGHTING AND RESETTNG	New	300.00	30.00
2	REMOVE AND REFIT REAR UNDERCARRIAGE	New	500.00	0.00
3	WHEEL ALIGNMENT	New	100.00	0.00
4	REMOVE AND REPLACE DAMAGED PARTS	New	800.00	800.00
5	REMOVE AND REPLACE DAMAGED PARTS	New	-	-
6	APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	New	800.00	0.00
7	WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS,REPAIRS INCLUDING CUT AND WELD,REALIGN BODY STRUCTURE	New	1,500.00	120.00
8	RESPRAY INCLUDING POLISHING AND WAXING ON THE CHANGED BODY PARTS,REPAIRED PORTORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
Gross Labour Cost (\$)			5,000.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >