

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001428/KPA3Q2
Date: 15/06/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100350624
Claimant Vehicle No :	SKA8289X	Insured Vehicle No :	SFA6838J
Date of Loss:	22/01/2021	Nature of Claim:	TP
		Claim No:	2651329035SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA8289X		
Make & Model:	DAIHATSU TERIOS, 1.5 4WD	Engine No:	1979113
Reg. Date:	24/12/2007 (Man. Year: 2007)	Chassis No:	JDAJ210G001058746
Colour:	White	Odometer:	179583 km
Engine Capacity:	1495 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/70 R16	Rear Tyre Size:	225/70 R16
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,053.24	1,433.37	1,619.87	53.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,810.00	890.00	920.00	50.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,863.24	2,323.37	2,539.87	52.23
Approved Total (Overridden) (S\$)		1,850.00		

Adjuster Report

	(S\$)	4,863.24	1,850.00	3,013.24	61.96
+ GST 7.00/7.00% (S\$)		340.43	129.50	210.93	61.96
Nett Amount (S\$)		5,203.67	1,979.50	3,224.17	61.96
+ Car Rental (4.0 x S\$100.00/day) (S\$)			400.00		
+ Doc/Search Fee (S\$)			2.00		
Nett Liability (S\$)			2,381.50		

INSPECTION

Date of Assignment: 29/01/2021

Date Inspected: 23/03/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Kgc Workshop Pte Ltd (AMK)
14 Ang Mo Kio Street 63, Blk B
Singapore 569116**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Cracked	605.00 FL	*560.00 FL
2	1		*FRONT BUMPER RETAINER RHS	Necessary	48.50 FL	*48.50 FL
3	1		*HEADLAMP RHS	Cut	725.50 FL	*659.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Repair	388.20 FL	*- FL
5	1		*FRONT FENDER RHS	Buckled	425.50 FL	*360.00 FL
6	1		*FRONT FENDER INNER SHIELD RHS	Serviceable	155.50 FL	*- FL
7	1		*FRONT GRILLE	Serviceable	405.50 FL	*- FL
8	1		*FRONT LOWER GRILLE	Serviceable	285.50 FL	*- FL
9	1		*FRONT FOG LAMP RHS	Serviceable	350.00 FL	*- FL
10	1		*FRONT FOG LAMP COVER RHS	Serviceable	85.20 FL	*- FL
11	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
12	1		*SET FRONT NUMBER PLATE	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,574.40	1,677.50
- List Item Discount on L Items 15.00/15.00% (\$)	521.16	244.13
Total Parts (\$)	3,053.24	1,433.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE ,REPLACE ,CUT ,WELD ,KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS	New	800.00	400.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT	New	800.00	440.00
3	WHEEL ALIGNMENT	New	80.00	0.00
4	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME	New	80.00	20.00
5	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	50.00	30.00
Gross Labour Cost (S\$)			1,810.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >